

# Select Inspect

Property Consultants, LLC

## Property Inspection Report

Prepared exclusively for:  
Client



at: 123 street; Allen, TX 75002



The greatest compliment I can receive is a referral from you,  
to a friend, family member, or coworker.

Thank you for choosing Select Inspect.

Sincerely,

*Bruce W. Carr*

214-770-6954

**Select Inspect Property Consultants LLC**  
2001 Reston McKinney, TX 75070  
**PROPERTY INSPECTION REPORT**

**Prepared For:** Client  
(Name of Client / Purchaser of service)

**Concerning:** 123 street Allen, Texas  
**(Address or Other Identification of Inspected Property)**

**By:** Bruce W. Carr; TREC #5281 ASHI Member # 211804 Wednesday, April 20, 2011  
(Name and License Number of Inspector) (Date)

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at [www.trec.state.tx.us](http://www.trec.state.tx.us).

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC-licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is not required to move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with all manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector will note which systems and components were Inspected (I), Not Inspected (NI), Not Present (NP), and/or Deficient (D). General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing parts, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another. Some items reported as Deficient may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards, form OP-I.

This property inspection is not an exhaustive inspection of the structure, systems, or components. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTION, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods. Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc.

These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

---

### ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

This report is prepared exclusively for the client named at the top of this document. Reliance of information within this document by third parties is not permissible. This report is non-transferable and is not to be used for insurance or warranty underwriting or reference, and is not acceptable for use by subsequent or potential buyers of this property, or any persons other than those named above.

Important related documents are provided with this report. The information at the end of this report and in the "Select Inspect Guide to Your Home Inspection" (available at [www.SelectInspect.com](http://www.SelectInspect.com)) is an integral part of this report, and should be kept with this report for future reference. Select Inspect performs the home inspection to the standards of the Texas Real Estate Commission ([http://www.trec.state.tx.us/inspector/rules\\_governing\\_inspectors.asp](http://www.trec.state.tx.us/inspector/rules_governing_inspectors.asp)) and standards of practice (<http://www.homeinspector.org/standards/default.aspx>) of the American Society of Home Inspectors [www.ashi.org](http://www.ashi.org), , unless otherwise noted.

Select Inspect does not make or imply any guarantees, warranties, nor does Select Inspect insure or warrant the future performance of any component, whether it is listed or not listed within this report. Warranties are available from home warranty firms, and should be purchased from one of your choosing, if desired.

We do not compare all components and conditions to determine if all components and conditions are compliant to past or current code requirements. We do not determine insurability of any part of the property. We do not guarantee to identify recalled components or systems. If the inspector suspects a component to be involved in a recall, we will attempt to identify the component and offer a route for you to find more information on that system. The Consumer Product Safety Commission (CPSC) website has a detailed listing of recalled products that you should examine if you are concerned.

Items marked only as "inspected" were found to be operating as intended, relative to age and function, and not having significant, obvious defect or unsafe conditions at the time of inspection. Items marked as "not inspected" were not inspected; if necessary, a comment as to why the component was not inspected will be provided. If a component is marked "not present", the item was not discovered installed and operational at the property.

If a component is listed "deficient", the component or condition was found to be amiss & or unsafe in the opinion of the inspector or as required by TREC & or ASHI standards. If the client has any concerns about items noted in the report the client should have an experienced professional in the related field examine all related components of that entire system, prior to closing. A qualified licensed, bonded professional of your choosing should be contracted to make all necessary repairs. After repairs have been made, the client should have the company or person performing the repairs provide documentation of all items examined, repaired / replaced, and provide a full report of the system. The client should obtain any and all available documentation and warranties regarding prior repairs and services of property components and conditions, and documentation for repairs and services resulting from comments within this report.

If an item is present in the property, but is not inspected the "NI" column will be checked and an explanation is necessary. Comments may be provided by the inspector whether or not an item is deemed deficient. This report may be electronically distributed by SIS and changes, deletions or amendments to the report of any type are strictly prohibited. It is recommended you obtain receipts and warranties for repairs resulting from this inspection.

Some conditions and components that we are required to note as "deficient" may be subjective priorities to you or the seller. It would be prudent to consult specialists hired for related repairs to determine priorities of potentially subjective repairs. We do not determine life expectancy of any component.

**REINSPECTION OF REPAIRS & RETURN VISITS TO THE PROPERTY ARE NOT INCLUDED** with the original inspection fee. Reinspection will cost a minimum of \$150 to return to the property for up to one hour, & \$100 per hour (\$1.6~ per minute) after the first hour at the property, & a fee of \$1 per mile round-trip. This does not include a written report of the reinspection; a written report will cost an additional \$50. Work performed by unlicensed contractors or amateurs **WILL NOT BE INSPECTED**.

If a trade requires licensing, a licensed contractor must perform & document the work.

Contractor should provide written documentation as to if the work is warranted; how long it is warranted; and if the warranty is transferable to the new owner. Regarding repairs not having documented evidence by a licensed company/tradesman present and readily available at the property during the reinspection, those items **WILL NOT BE INSPECTED**.

For example, if any plumbing is done; it shall be performed & documented by a licensed plumber; if any electrical is done, it shall be performed & documented by a licensed electrician; if any heating, air conditioning, & or ducting work is done, it shall be performed & documented by a licensed HVAC specialist; any framing, roofing, etc shall be performed & documented by a licensed contractor in that related field. It is the full responsibility of the paying party to provide all necessary documentation at the time of the reinspection.

This inspection, the report, and all other related documents are NOT to be used to determine acceptability for insurance underwriting, loan approval, or for any other similar capacity. All related documents are solely for the use of the purchaser/client. Insurance and lenders must arrange their own inspection to determine suitability for their needs. Reliability on this report for insurance, or loan related matters is strictly prohibited.

*Residential & Commercial  
Property Inspection*

Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

**Report Identification 123 street; Allen, TX**

**Table of Contents**

**Yellow** Highlighted sections contain one or more conditions noted as **deficient** by the standards of TREC, ASHI, and/or in the professional opinion of your Inspector. Refer to the body of the report for important details of discovered conditions.

**I. STRUCTURAL SYSTEMS ..... 5**

- A.1. Foundation.....6
- A.2. Structure.....7**
- B. Grading and Drainage.....8**
- C. Roof Covering .....9**
- D. Roof Structure and Attic.....10**
- E. Walls (Interior and Exterior).....12**
- F. Ceilings and Floors.....14**
- G. Doors (Interior and Exterior).....14**
- H. Windows.....15**
- I. Stairways (Interior and Exterior).....16**
- J. Fireplace / Chimney.....16**
- K. Porches, Balconies, Decks, and Carports (Attached) .....17
- L. Flatwork (Driveways, Sidewalks) .....17
- M. Other (i.e. foliage, retaining walls, other structural related) .....17

**II. ELECTRICAL SYSTEMS.....18**

- A. Service Entrance and Panels .....18**
- B. Branch Circuits- Connected Devices and Fixtures .....19**

**III. HEATING, VENTILATION, AND AIR-CONDITIONING SYSTEMS.....21**

- A. Heating Equipment.....21**
- B. Cooling Equipment.....22**
- C. Duct System, Chases, and Vents.....23**

**IV. PLUMBING SYSTEM .....23**

- A. Water Supply System and Fixtures.....23**
- B. Drains, Wastes, Vents .....24**
- C. Water Heating Equipment .....25**
- D. Hydro-Massage Therapy Equipment .....25

**V. APPLIANCES .....25**


- A. Dishwasher.....25**
- B. Food Waste Disposer.....26**
- C. Range Exhaust Vent.....26
- D. Ranges, Cooktops, and Ovens .....26
- E. Microwave Oven .....26
- F. Trash Compactor.....26
- G. Mechanical Exhaust Vents and Bathroom Heaters (includes utility room fan if present).....26**
- H. Garage Door Operator(s).....27**
- I. Door Bell and Chimes .....27**
- J. Dryer Vents.....27

**VI. OPTIONAL SYSTEMS .....27**

- A. Lawn and Garden Sprinkler Systems.....27**
- C. Outbuildings .....28
- E. Gas Supply Systems.....28**

**LIMITATIONS, EXPLANATIONS, & DEFINITIONS.....29**

**DIGITAL PHOTOGRAPHS; Supplementary to this Inspection Report .....33**



Every comment in this report and all related documents is very important and you should read every word.

Additional web-based documents or printed pages were delivered/linked with this report. Read them very carefully. This report is not complete without all attachments.

It is important to understand that this inspection is a first step towards gaining a partial understanding of the property condition. The inspector uses a systematic and limited method of inspection that attempts to identify and report issues of concern however the inspection is time limited, general in nature and subject to human error. The inspectors opinion can vary from the opinion of other persons. The inspection is very good at reducing risk but it does not eliminate risk. If these limitations or this service does not meet your needs call our office about comprehensive inspection services.

This inspection does not inspect for the presence of mold and microbiologicals. If the inspector sees a suspect condition (fungus) it may be reported as a supplemental and incomplete comment but it does not mean the inspector saw and reported all fungus/mold conditions. Unless stated, the inspection does not determine prior wetting / flooding and / or insurance histories and any comment regarding such would be incomplete. The inspector does not use special tools to detect moisture in inaccessible areas.

This is not a "code inspection", although our standards and procedures are based primarily on the IRC, UBC, NEC, UPC, etc. Many comments will, however, cite specific code references in order to support the inspector's findings and the inspector's opinion regarding some (not all) deficiencies.

All deficient drainage conditions should be professionally repaired, and the home frequently monitored for movement; if movement is observed or if you are concerned at any time about the foundation or structural integrity of the home, consult an engineer. This home most likely will cost you more than your vehicle(s); assuming you regularly have your vehicle checked and professionally serviced, you should plan to provide similar regular maintenance and checkups on your home/property as well. Routine maintenance of structural, mechanical, and other components in or affecting the integrity and or performance of the home, will assuredly increase the service life of your property and its components.

Select Inspect cannot prioritize for you; there are too many variables for every item mentioned in the report, please do not ask. Whenever possible, it is recommended that all repairs be made. As a minimum, Select Inspect strongly recommends that any and all safety and health issues including but not limited to: fire, safety, electrical, HVAC, moisture intrusion / leakage, carbon monoxide, natural and or propane gas, fungal, and structural concerns be comprehensively examined by a licensed or occupationally certified specialist in the respective field. Complete and appropriate permanent repairs should then be made without delay.

Deficient conditions will be reported in this document that are noted as *incorrect, not ideal or not functioning as intended*. However, from a performance standpoint immediate repair needs may be subjective regarding deficient components, systems, items that are not causing safety, fire, or health risks; are not structurally significant; and/or are not financially excessive. Monitor closely and arrange repair/improvement when feasible; or if you are unwilling/unable to accept the risk of monitoring and maintaining components of the property, you should arrange professional repair and obtain warranties prior to closing.

IMPORTANT: A contract (Home Inspection Agreement) was provided and signed by you or your representative at the time of inspection. The contract contains important information related to the scope of this inspection, limitations, and other comments. If you have not already, please read the contract in its entirety, and contact us if you have any questions; 214-770-6954. Your business is important to me, and I appreciate your choosing Select Inspect.

## I. STRUCTURAL SYSTEMS

### Site Conditions & Persons Present During Inspection:

Approximate year built: 1990; [per MLS, CAD, or other documentation / person(s)]

Person(s) Present:     Client(s)     Selling Agent     Occupant / Seller     Listing Agent

Home was:     Occupied     Vacant     Unoccupied with Furnishings or storage / staging

Additions/modifications to the structure:     Yes     Not discovered     Suspected; not verified

Faces Primarily:    North    Temperature: 60 - 70 Degrees (approximate at beginning of inspection)

Weather:     Dry     Rain     Stormy     Ice / Snow     Dark / limited lighting, morning, evening

Visibility:     Sunny     Partly Cloudy     Cloudy / Overcast     Moderate Wind     High Wind

I NI NP D

### A.1. Foundation

Foundation Types discovered at property: Slab on grade

Comments (An opinion on performance is mandatory.) The inspector will in most cases only comment on the foundation as "inspected. In the event "excessive" structural movement is suspected, only a licensed structural engineer will have the authority to determine if foundation "repair" is justified. Only an engineer has the education and certification to accurately determine the extent of foundation movement and to prescribe any necessary repairs. The inspector will make note of conditions indicating foundation movement and possible contributing factors. The inspector will form an opinion that based upon his findings, reflects whether or not a likelihood of need for repair will be justified. The inspector will document whether in his opinion, the foundation appears satisfactory, is questionable, or likely needs repair. If the inspector documents any opinion other than satisfactory, it would be prudent to consult an engineer or other foundation specialist of your choosing to evaluate site and structure. If you have any concerns, or you are unwilling to accept risk of maintaining the site and structure, you should hire an engineer to fully evaluate the site and structure for conditions needing improvement and or repair. Refer to the limitation information at the end of this document and consult your "Guide to Your Home Inspection" for more important related information.

In the inspector's opinion, the overall performance of the foundation/structure does not appear abnormal or excessive, by common standards.

Stability & or future performance are not guaranteed. Recommend you take one of the following options:

Accept the home AS IS & provide a consistent, regimented moisture maintenance program including correction of any high soil, poor drainage, moisture intrusion, & foliage intrusion conditions at the property. If you are unwilling to take responsibility for corrective maintenance & or if you are unwilling to accept any & all risk involved with improperly maintaining or failing to maintain the property understanding current & potential condition, select option #2.

OR

Prior to closing: Hire a professional Structural specialist or Engineer to examine the entire property & structure that s/he may then provide an opinion regarding permanent corrective actions, if such action is determined to be necessary. Opinions between engineers may differ, & second opinions may be a prudent decision.

The following conditions were discovered at the time of inspection:

The home appears to have been patched and painted, re-carpeted, and or remodeled since the time of construction. Evidence of cracks / movement indications and or insect & moisture damage conditions may have been covered up with remodeling efforts. Refer to the seller's disclosure for information regarding remodeling, repair, and property history.

Indications of commonly seen stress / settlement were discovered, including;

- **INTERIOR:**
  - Drywall nails have popped through the painted interior surfaces. This is common, & is related to normal settling & shrinkage movements.
- **EXTERIOR:**
  - Closed masonry/veneer cracks (*less than 1/8" wide*) discovered at north, northeast, northwest, west, east, south

Movement Indications **TREC considers as adverse performance** were discovered, including;

- **INTERIOR:**
  - Thin/closed Interior wall cracks discovered above/below doorways or windows at the east bedroom & closet
  - Upper wall / ceiling crack(s) discovered at family room southwest & northeast, & bedrooms are often from roof structure settlement & not always foundation related
  - Trim separation/stress at ceiling, wall, floor, door casing/trim or other joints discovered at the study, foyer, dining room
  - Garage concrete is cracked. Thin cracking is common, though larger cracks can indicate excessive or uncommon movement. Garage concrete cracks did not appear to extend through the beam(s) at one or more location; these should be closely monitored.
  - Unsquare/difficult interior doors that rub flooring & or door frame(s) discovered at the upstairs bathroom
  - Doors have been modified to accommodate unsquare jambs
  - Binding, out-of-square, non-latching, warped, or twisted doors or frames & or out-of-square wall openings or separations between the framing door frames at the upstairs bathroom, master, & east bedroom.
  - Separation at interior window framing discovered at the master bathroom & northeast bedroom.

- Binding, out-of-square, non-latching, warped, or twisted windows or frames & or out-of-square wall openings or separations between the framing & window frames
- Sloping floors discovered at the upstairs- refer to interior structure comments below.
- Common cracking of slab foundations is possible & common, even on young homes. Concrete below flooring may be cracked; this cannot usually be determined without removing floor coverings. Conditions beneath flooring remain undetermined

**EXTERIOR:**

- Open masonry/veneer cracks/separation (*greater than 1/4" wide*) discovered at the northwest
- Separation at frieze-board, veneer, & or framing discovered at the northwest & master bathroom window
- Exterior evidence of separation at window framing & veneer discovered at various perimeter locations
- Out-of-square wall openings or separations at wall openings or between the cladding & window/door frames
- Sloping & or unsquare/difficult exterior doors indicate some degree of structural movement.
- Doors have been modified to accommodate unsquare jambs
- Past garage separation is indicated by sealant at the joint of the garage door frame & adjacent veneer.
- Slab or perimeter beam (foundation) cracks/fissures noted at the west.

**Discovered conditions that TREC requires to be reported as deficiencies include:**

- None discovered

I NI NP D

**A.2. Structure:**

Structure comments include sub floor, wall, & ceiling structures of the building where conditions other than foundation issues appear to be contributing to deficiencies in the opinion of the inspector; please refer to section D of this report for comments related to roof & attic structure.

**SUB FLOOR:**

Upstairs floor deflection discovered at the upstairs hallway southwest, east bedroom, northeast bedroom closet, & southwest bedroom. Areas appeared to be in line with load paths from roof structure which would imply structural settlement/stress, & not necessarily foundation stress.

**INTERIOR WALL & CEILING STRUCTURE:** often including, but not limited to conditions of foundation stress and or roof/attic structure stress.

Moisture damage & fungus exist at the dining room window & east bedroom. Moisture intrusion/moisture staining exists at the southwest bedroom, upstairs hallway, master bathroom. There may be some moisture damage & or compression/related structural conditions that were concealed & not discovered. Extent of damage is undetermined in concealed wall spaces; undetermined conditions include but are not limited to the presence and or condition of fungus, insulation, framing. We do not perform mold testing, and did not take fungus or air samples from the home. If you are concerned about health related issues, we recommend that you consult an indoor air quality firm for evaluation and options for cleaning. Researching and evaluating various firms and their methods for remediation would be prudent, if you plan to pursue those measures.

Structural stress is implied by cracks & unsquare doorways in the home.

**EXTERIOR WALL STRUCTURE:** often including, but not limited to conditions of foundation stress and or roof/attic structure stress.

Master bathroom box window had visibly shifted; openings/separation at the interior glass block, bathtub(s) ledge, tile, & drywall/framing indicates structural stress.

Exterior window sills did not have a recommended 15° slope for drainage at multiple locations; slope at random locations was approximately 1, 6, 8° Repair options may be limited. Condition & appropriateness of flashing & substrate components is undetermined.

Mortar at multiple window sill/ledges, & various areas of erosion should be tuck-pointed; missing mortar & pits/openings are prone to water infiltration & extended freeze-thaw conditions & further deterioration of mortar & brick.

Shed & stacked brick at the west obstructed siding/trim some foundation & lower wall areas.

Condition & appropriateness of the wall voids & related components such as vapor barrier, air space, drainage plane, potential mortar/debris obstructions, etc are mostly/all not readily accessible & not inspected. Incorrect conditions may allow moisture intrusion & or inability of the walls to properly dry from condensation. This could lead to fungal spore accumulation & related air & moisture damage issues.


Flashing was not seen at lintel locations above windows & doors; the lintels may be "L" channel, though without invasive measure this could not be determined. Condition & type of lintel & presence/absence of appropriate flashing/& drainage plane remains undetermined.

Weep openings appeared to have been omitted above brick faced doors & windows (may be related to moisture intrusion at the dining room & study windows), & were not as frequent at all foundation locations as currently recommended. Such is not recommended, as these provide drainage of condensation from within

Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

the wall voids.



**Other Structural Related:**

Soil moisture/drainage conditions were discovered that may adversely affect the structure. Refer to the grading/drainage comments in the next section.

NOTE: most undesirable foundation issues in north Texas are caused by poor moisture maintenance around the home. refer to the next section "Grading & Drainage" for information that may be relative to foundation movement at this property.

Foliage conditions were discovered at one or more exterior location that may adversely affect the structure. Refer to [section I.M. Other Structural / Foliage](#) comments later in this report.

Additional Information:

This report, including the foundation & structural opinion, represents one inspector's opinion of visible evidence present and accessible on the day of the inspection. Future performance of the foundation and structure is not warranted. Regular maintenance is needed to keep the foundation from unusual movement or failure. Information concerning moisture maintenance and foundation control measures is at the end of this report.

The inspector's opinion, based on observations of physical evidence, is opinion only; additional information regarding the foundation and structure can be obtained through consultations with a professional engineer of your choosing. In the limited time the inspector is at the property, it is difficult to determine whether observed conditions are ongoing, have recently occurred, or at what time in the past they were active. We recommend you monitor the structure periodically in all cases. If issues are discovered, you should contact a specialist to examine the situation, so they may prescribe options for permanent repair. Opinions of performance and methods of maintenance, repair, or monitoring vary person to person.

I NI NP D

**B. Grading and Drainage**

Soil conditions at the time of inspection:	Damp / Moist _____
Some areas (if different) were noted as:	moist / acceptable

*Comments: Underground components are not inspected; sub-grade conditions remain undetermined. Drainage conditions are subject to change, considering amount and frequency of rains, seasonal changes, irrigation system settings, erosion. This inspection does not investigate or identify sub-grade water tables, springs, or elasticity qualities of soils. Grade conditions should be monitored through the life of the home. Prior drainage issues at the property cannot usually be identified by this inspection. Refer to the seller's disclosure for possible information regarding past drainage problems and or correction. Refer to the limitation information at the end of this document and consult your "Guide to Your Home Inspection" for more important related information.*

**Soil Grading and Drainage: Deficient**

- ✦ Planter / garden areas at the front exhibit poor drainage ability. Consult a drainage specialist or engineer for options.
- ✦ Area(s) at the rear porch are located between the home's exterior foundation edge and sidewalk or similar flatwork is lowered from the concrete and appears to be conducive to or was confirmed to be retaining water and or having poor drainage ability. These conditions are conducive to adverse performance of the structure/foundation. Consult a landscape-drainage specialist for options.

Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

- ✦ Area drain cover at the west is damaged.
- ✦ The routing and condition of sub grade drain systems are undetermined, as they are most / all buried and inaccessible. Refer to the seller's disclosure for possible information regarding this item.

**Roof Drainage/Guttering: Deficient**

- ✦ Gutters are in disrepair. Removal or replacement is recommended. The following conditions discovered:
- ✦ Gutter-downspouts/drains should terminate at least 6 feet away from the home. This is intended to control erosion that can adversely affect the foundation; especially in areas of expansive soils or easily eroded soil such as sandy loam. However, above ground extension components are often obstructive to lawn equipment and traffic and may be prone to damage. As long as water is directed to an appropriate location at least 6 feet from the home, the need for extensions is very subjective.
- ✦ Some guttering has debris that should be cleaned to prevent congestion of the gutter-downspouts. This indicates that the section(s) discovered may not adequately slope toward the gutter-downspout(s)
- ✦ Gutter-downspouts were noted as congested. Cleaning and maintenance is recommended.
- ✦ Gutter-downspouts were noted as damaged. This may contribute to congestion. Repair is recommended.
- ✦ Some erosion has occurred below the gutter-downspouts. Recommend repair of gutters, replacement and compaction of native soils at the eroded areas (sloping away from the home, and not above the foundation edge), and adding stones or similar to disperse rain water.
- ✦ Splash blocks, stones or extensions should be used at gutter-downspouts to prevent erosion. Erosion evidence exists. Gutters should dispense water at least 6 feet away from the home
- ✦ Gutters sag or do not slope properly.
- ✦ Seam leaks were noted at various perimeter locations.
- ✦ Incorrect slope of guttering was noted at various locations. The components should slope downward to the drain ports and gutter-downspouts.

I NI NP D

**C. Roof Covering**

Roof Material:  Composition  Wood Shingle / Shake  Tile  Roll-Out  Slate  Artificial slate

Roof Inspected from:  Walking Roof Surfaces  Ground with Binoculars  Ladder at Eaves

Most accessible  Some areas Inaccessible  Most Roof areas Inaccessible

Too Steep / High  Wet / Ice / Slippery  Deemed unsafe to walk - injury/damage risk

*Comments: This inspection does not determine past hail damage, remaining life expectancy, or insurability of the roof systems. All areas in North Texas are subject to hail storms, and you should verify acceptability of any questionable conditions by your insurance / home warranty provider prior to closing. If it is not raining at the time of inspection, it is unlikely that the inspector can positively identify ongoing leakage issues. All roof systems should be monitored during / after rainy weather and or hail. Condition of underground or otherwise inaccessible guttering components remains undetermined. Refer to the limitation information at the end of this document and consult your "Guide to Your Home Inspection" for more important related information.*



**Roof Coverings: Deficient**

- ✦ (multiple related image(s) at the end of this document)
- ✦ The roof appears worn/aged and may be nearing end of its expected lifespan. Suspected hail/weather damage evidence and or aging/wear was noted at the roof surfaces, fencing, and air-conditioner condenser coils. It would be prudent to ask for your intended insurance provider to view the roof prior to closing to prevent unexpected underwriting issues. If roof repairs are made, any other roof related deficiencies noted in this or related specialist's report(s) including: framing, sags, deflection, flashing, flues, ventilation, penetration issues should be corrected at that time.
- ✦ The water heater flue was too short & or too close to a vertical wall/window. "B vents" should be minimum 2 feet above any vertical surface within 8 horizontal feet of the flue; (IRC 2426.6.5 & UMC 806.4)
- ✦ The dead valley at the northeast has marginal / poor slope, directs water into the decaying/low trim/siding, and may not drain properly. This is conducive to debris accumulation and potential moisture intrusion. Repair is recommended.  
*"Dead valley" description: A converging valley feature with a vertical wall joined by flashing at a convergence of one or more roof angles/valleys; this feature is commonly associated with a higher risk for leakage, due to water being directed toward rather than away from a wall, roof, and or flashing convergence. The roof, attic, and interior areas surrounding and below this feature should be inspected during different weather periods for leakage. These valleys will also create a higher risk of ice damming and potential moisture intrusion behind the shingles in winter.*

Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

- Siding at roof edge walls is lower than recommended, and touches the roof surface. Rot was present at one or more of these valley / siding features. Repair is recommended. Ideally, the siding would be a few inches above the roof, to prevent moisture from soaking into the bottom and decaying the siding.
- Flanges collars were splitting or otherwise amiss at plumbing penetrations. Repair with other roof corrections.
- Flashing at a vertical wall / roof joint is amiss / incorrect at the northeast and is a potential moisture intrusion risk.
- Flashing is uplifted at the rear porch & behind the fireplace chimney. Recommend securing and sealing as needed to reduce moisture intrusion potential.
- Kickout flashing was deficient or not present at multiple required locations. moisture damage at roof deck was discovered at related garage northeast & northwest. This can allow moisture intrusion to be directed behind the siding, rather than to the exterior. Recommend modification / correction of the flashing, or appropriate sealant, if such can be done to adequately correct the condition.



- NOTE: Suspected hail/weather damage evidence and some suspected related damage was noted at the roof surfaces. Check with your insurance company prior to closing, to ensure the roof will be accepted pending any repairs they may require. It would be prudent to ask for the seller's insurance to examine the roof prior to closing as well.
- Moisture intrusion evidence noted at flue & vent penetrations; correction/improvement of this and other related conditions is recommended; sealant is considered a "temporary repair".
- Moisture intrusion & rot noted at the eave area & adjacent attic components - upper east.
- Protruding nail(s) should be removed and the opening in the shingle then sealed. Condition was noted at the rear porch
- Open-faced (uncaulked) fasteners exist Though technically incorrect this is commonly found, even on new homes. Correction is generally simple, inexpensive, and is recommended.
- Multiple damaged & some missing shingles were noted. Tree damage noted at the master southeast.
- Evidence of prior repair / repair attempts was discovered at roof covering materials, flashing details, skylights, and or roof penetrations in readily accessible locations. Evidence of repair is typically implied by shingles of variant tone, type, or quality; by caulking, tar, other type of sealant; and or obvious visual modification of roof components.
- Roof fasteners were not all visible; not readily accessible without lifting shingles and potentially causing damage. The condition and appropriateness of roof covering & sheathing (felt) fasteners was not inspected and is undetermined, except if noted otherwise and listed specifically in other commentary within this section of the report.

I NI NP D

**D. Roof Structure and Attic**

Framing style:	Conventional; ___
Type of Underlayment observed:	Plywood or OSB ; ___
Viewed From:	Walking decked areas Some areas not safe for direct access
Insulation Type:	Batt (roll-out) and Blown ; Fiberglass
Approximate Average horizontal Insulation depth- ceilings	6 - 8 inches
Approximate Average vertical Insulation thickness- walls	6 inches or less

Ventilation:

- Roof / Box    Turbine    Eave /Soffit    Gable    Electric    Ridge

Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

Report Identification 123 street; Allen, TX


Obstruction of access / vision
 Stored items    Low clearances    HVAC items    Other

 Lack of deck/attic flooring at some locations    Animal(s) suspected / discovered


*Comments: Attic components are observed in a cursory fashion. This includes only those areas and components that are safely accessible and visible at the time of inspection. Obstructions within the attic may include, but are not limited to: stored items; HVAC, plumbing, and electrical components; low clearances; lack of attic flooring; small, obstructed, or inaccessible attic hatches. When possible, the inspector will identify known obstructions, and make every effort to access areas when conditions to do so safely are available. Refer to the limitation information at the end of this document and consult your "Guide to Your Home Inspection" for more important related information. Advisory Use caution when entering/exiting or moving about in attic areas.*

#### Attic Access: Deficient


- ✦ The garage attic(s) did not have access present. Attic access opening shall be provided to attic areas that exceed 35 sq ft and have vertical height of 30" or greater. Rough framed opening shall be at least 22" X 30" and located in a readily accessible location (IRC 807). Conditions in inaccessible locations remain undetermined, including moisture intrusion, framing, insulation, etc. Consider a ladder or short door from the southwest bedroom-south wall
- ✦ The attic ladder(s) does not extend properly and is unsteady / potentially unsafe. Correction / improvement would be prudent.
- ✦ Ladder hardware (nuts, screws, etc) is loosely secured or missing at stair components. The unit is unsteady and repair would be prudent to reduce risk of failure and injury.
- ✦ Attic access(es) was inadequately insulated & or seals poorly. Energy loss exists



#### SCUTTLE HOLE COVER



#### KNEE-WALL DOOR



#### Attic Structure: Deficient

- ✦ Moisture damage exists at the east upper eave. Repair is recommended.
- ✦ There was not a clear, solid (having no gaps), unobstructed 24" floored pathway to the mechanical system(s) from the access. This is considered a safety risk for persons examining or servicing the mechanical systems (HVAC, water heater, etc).
- ✦ The attic(s) were not fully accessible due to lack of decking & HVAC obstructions. The attic areas were inspected from limited decked areas only.

Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

Report Identification 123 street; Allen, TX

- ✦ NOTE: "T-bracing" was amiss. Significant deflection or similar issues were not discovered at related locations. Recommend monitoring and considering correction/improvement of the conditions when the roof is replaced in the future. Technically, 6 foot or longer struts that are 45 degrees or more should be "T" braced for added strength.

#### Attic Insulation & other accessible insulation: Deficient

- ✦ Insulation was missing, fallen from a vertical wall, or otherwise deficient at the upstairs hallway & various random small areas seen in the attic. Correction / improvement would be prudent.
- ✦ Thermal imaging indicated areas that may have deficient insulation, air barrier/sealant, & or ventilation deficiencies at study, kitchen, master closet, master bedroom & bath, northeast & northwest bedrooms & commonly found general areas including vaulted corners (walls & ceilings), framing convergences, perimeter floor sills, electrical switches & receptacles adjacent exterior walls, & plumbing & HVAC chases.
- ✦ Insulation is inspected in a very general manner from limited accessible locations; Conditions in not readily accessible/inaccessible locations remain undetermined; this is general in nature & is not a comprehensive investigation of all areas.

#### Attic Ventilation: Inspected

- ✦ Abnormal conditions were not obvious at the time of inspection. Monitor and maintain.

### I NI NP D

#### E. Walls (Interior and Exterior)

Interior Wall Structure:  Wood framing  Metal Framing  Brick / Masonry

Interior Obstructions:  Storage  Furnishings  Décor  Other

Exterior Obstructions:  Foliage  Storage  Deck  Building  Other

Exterior Wall & Trim:  Brick  Stone  Masonry Stucco  Artificial Stucco  Wood / Pressed Wood

Wood-Fiber / Hardboard  Cementitious Fiberboard  Vinyl and or Aluminum Siding

*Comments: This inspection does not include or report cosmetic related conditions. Refer to the limitation information at the end of this document and consult your "Guide to Your Home Inspection" for more important related information. Granite countertops, if present, are not tested for presence of or levels of uranium or radiation. Related information can be found at: <http://www.selectinspect.com/links1.htm#radonlink>*

#### Interior Walls: Deficient

- ✦ Sealant needed at the top tile/panel edge at the wall of the shower(s) to reduce potential for moisture intrusion and fungal accumulation at the shower substrate (between the shower and walls)
- ✦ Drywall is missing or damaged at the garage ceiling and or walls. This detracts from separation / protection requirements for attached garages. Drywall repair is recommended.
- ✦ Previous repair evidence was observed at the laundry room. The cause for need of repair is undetermined. Repairs can be related to remodeling, foundation movement, moisture, insect damage, or other undetermined causes.


#### Cabinetry/Countertops: Deficient

- ✦ Cabinet door was inadequately secured at the laundry room.
- ✦ Moisture history was indicated or suspected by stains, damage, and or swollen materials below kitchen & master bathroom sinks. Presence of fungus and extent of damage is not determined in not readily accessible areas such as wall voids or behind/below cabinets.
- ✦ Powder bath sink cabinet was inadequately secured.

#### Exterior Walls: Deficient

- ✦ Moisture damage exists at the master bathroom, chimney, overhead door lower left, above breakfast nook window, northeast eave, east eave, & garage side doorway. Damaged/deficient wood-based components should be removed and replaced; all six sides of the wood piece(s) should be primed and painted. Cellulose material should be kept caulked and painted to resist decay. Rot is conducive to wood destroying insects and continued decay of adjacent cellulose components. Adjust irrigation to not directly spray the home. Presence or extent of damage at hidden components is undetermined.
- ✦ Exterior lights should be properly sealed to prevent moisture intrusion and related corrosion / overheating possibilities of the electrical components. NEC 410-4 & IRC E3905.
- ✦ Exterior electrical receptacles (outlets) should be properly sealed to prevent moisture intrusion and related corrosion / overheating possibilities of the electrical components. NEC 410-4 & IRC E3905.
- ✦ Recommend caulking vertical & horizontal siding / trim joints & all nail heads at siding & trim. This is a periodic maintenance item.

- ✦ Sealing is needed at the air-conditioner & irrigation component penetrations at the exterior wall
- ✦ Windows need caulk touch-up / repair at exterior perimeters
- ✦ “Z” flashing was not present or not visible, or otherwise deficient above wood trimmed windows/doors. This is recommended to direct water out and away from the interior substrate/envelope. The flashing is commonly omitted; this would be more easily installed if/when trim is replaced.
- ✦ Siding at one or more veneer walls at a roof line is lower than recommended, and touches the roof surface. Rot was present at one or more of these valley / siding features. Repair is recommended. Ideally, the siding would be a few inches above the roof, to prevent moisture from soaking into the bottom and decaying the siding.



- ✦ NOTE: "Hard-board" type siding and or trim was noted at some or all exterior locations. Some of these "pressed wood-fiber" products have been involved in litigation, due to the propensity of this material to absorb moisture and subsequently decay. These products must be kept well caulked and painted to prevent moisture intrusion and failure. You should keep all foliage trimmed that it does not touch the siding / trim. It is recommended to keep lawn irrigation adjusted to not directly spray the siding / trim. Recommend repair of conditions including:

- Rotten, swollen, or otherwise moisture damaged components
- Fungus/mildew present at siding and or trim
- Material is lower to roof than the recommended minimum 2"
- Fasteners retracting and or trim / siding was poorly secured
- Siding / trim was warped, bowed, or buckled
- Foliage touching siding and or trim at walls /eaves
- Caulk repair is needed at component junctions (siding, trim joints)
- Consult one or more qualified siding contractors for repair options and price quotes. The condition of substrate, framing, insulation, and other materials in inaccessible areas remains undetermined. If / when repairs are made, you should have related areas behind the siding examined for repair needs. The specific type / brand or potential existence of a manufacturing defect is undetermined. Whether or not the product(s) on this home is currently or has previously been involved in litigation is undetermined.

  
 Residential & Commercial  
 Property Inspection

Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

**Report Identification 123 street; Allen, TX**

I NI NP D

   **F. Ceilings and Floors**

- Ceiling Structure:  Wood or engineered wood framing  Metal Framing
- Floor Structure:  Concrete Slab  Wood Framing and Subfloor over crawl space
- Built-up Wood over Concrete (Screeded)  Metal Framing over crawl space
- Obstructions:  Floor coverings  Furnishings  Storage / Personal Items  Sub floors

Comments: This inspection does not include or report cosmetic related conditions. Refer to the limitation information at the end of this document and consult your "Guide to Your Home Inspection" for more important related information.

**Ceilings: Deficient**

- ✦ Moisture evidence was indicated by stains at southwest bedroom, master bathroom, master bedroom, east bedroom, upstairs hallway. Presence of fungus and the extent of damage is not determined in inaccessible areas. Moisture source and any damaged insulation in the attic(s) above should be identified and permanently repaired.

**Floors: Deficient**

- ✦ Carpet was inadequately secured at the bottom of the stairs; trip hazard
- ✦ Tack-strip was moisture stained at the northeast corner of the dining room.

I NI NP D

   **G. Doors (Interior and Exterior)**

- Obstructions:  Storage  Furnishings  Vehicle(s)  Locked  Other

Comments: This inspection does not include or report cosmetic related conditions. Refer to the limitation information at the end of this document and consult your "Guide to Your Home Inspection" for more important related information.

**Interior Doors: Deficient**

- ✦ Door(s) do not latch properly at the east bedroom
- ✦ Interior doors were unsquare and self-swing open / closed at the master. Repair needs are subjective.
- ✦ Northeast bedroom door is damaged.

**Exterior Doors: Deficient**

- ✦ Garage side door is moisture damaged/rotting
- ✦ Damaged weather-stripping exists at the master patio door.
- ✦ Garage/laundry room handle was inadequately secured.
- ✦ **ADVISORY:** Current standards recommend the door(s) from the home to an attached garage be self-closing. The door(s) at this home did not meet this recommendation; some municipalities do not enforce this. However, I recommend improvement to help prevent fumes (specifically auto exhaust) in the garage from entering the living area, and to maintain the required "attached garage-to-home separation", if such a separation is present, in tact, well sealed, & functional. Some call this a "fire-wall", but all components involved would have to have an approved fire rating, though a proper "separation" will offer some resistance & increased burn time before compromising the residence. If there is an attic with a common ladder door assembly in the garage, your separation wall is likely already compromised.

**Garage Door: Deficient**

- Garage Door Type:  Metal  Wood  Fiberglass / Plastic / Composite  Insulated

- Garage Door / Frame:  Overhead  Modern  Hinged  Antiquated

- ✦ The garage door(s) falls closed when the garage door(s) was released from the garage door operator and placed approximately 4-5 feet above the floor. The springs may need adjustment/replacement. According to The Door & Access Systems Manufacturer's Association International (DASMA); doors should not offer more resistance or more force than what is applied by the person raising/closing the door. Standard testing protocol provided by The Door & Access Systems Manufacturer's Association International (DASMA); <http://www.dasma.com/PDF/Publications/TechDataSheets/CommercialResidential/TDS167.pdf>
- ✦ Warning labels for the garage door springs were painted, not present or otherwise deficient.
- ✦ Lower panel was bent; immediate corrective/improvement needs may be subjective.

- It is recommended to read and follow all manufacturer's labels, warnings, and maintenance information. Following these guidelines will provide for safer conditions, and can extend the life of the unit(s) and components. This refers to garage doors and garage door operators.

I NI NP D

   
**H. Windows**

Window Type:	Multi-pane, Insulated __ __
Window Framing:	Metal __ __

Obstructions:
 Storage  Furnishings  Window Treatments / Shutters  Foliage  Poor lighting conditions

Comments: Though some comments may be made regarding safety glass, you should understand that these comments are limited. This inspection departs from conditions and current standards regarding safety glass, and are not respective of all possible conditions. Regulations vary city to city, and frequently change. If you are concerned, please consult a glass specialist, familiar with requirements in your area. Refer to the limitation information at the end of this document and consult your "Guide to Your Home Inspection" for more important related information.

**Windows: Deficient**

- Failed (foggy) double pane windows were noted or are suspected. The condition may not greatly reduce insulating efficiency, and in some opinions is more a cosmetic issue. A window specialist should examine these and all windows in the home to prepare a quote for replacement if replacement is desired. Due to dirty windows, obstructions and lighting conditions, some seal failures may have gone un-noticed. Failed or questionable windows exist at 40 discovered locations- as follows:
  - Breakfast nook 2
  - Dining room 4
  - Family room 5
  - Northwest bedroom 4
  - Master 5
  - Southwest bedroom 2
  - Master closet 2
  - East bedroom 2
  - Study 6
  - Northeast bedroom 6
  - Foyer 2
- Window glass is cracked at the east bedroom. Correction / improvement would be prudent.
- Security components should not have been installed at the bottom frame of the windows, as this compromises the integrity of the manufactured windows' ability to keep water out of the wall void. It is likely that this installation has created an opening in the moisture barrier/window flashing; and that too is likely compromised. Small openings around the sensors may be prone to moisture intrusion into the wall void and adjacent materials. Check each window, Seal and repair deficiencies where discovered, and monitor- repair if necessary in the future. The condition voids manufacturer warranty in most cases. Presence & or extent of moisture damage & fungus in the wall void below & adjacent these areas is undetermined.
- Brick sill is amiss and needs mortar repair at various locations.
- Moisture intrusion was indicated by staining, fungus, and or damaged building materials at dining room & study interior window perimeters- upper & side drywall. Moisture intrusion can be conducive to fungus, rot, and wood destroying insects. The condition appeared excessive. Correction/improvement of this and other related conditions is recommended. The source of moisture should be identified and permanently corrected.
- Moisture evidence was indicated by staining, damage, and or swelling at interior window drywall and or sills at various locations. This appears to be from condensation, rather than leakage; metal windows condense more than vinyl clad. Window condensation is often caused/contributed to by inadequate house ventilation; such may also indicate poor indoor air quality. Ventilation deficiencies may be in the entire home, or more prevalent in certain areas of the home; consult a knowledgeable HVAC contractor for options.
- Various screens were damaged
- Glazing has hail/impact damage at south, west, & north areas.
- NOTE: The upstairs window(s) have a lower open edge of less than 24" above the interior finished floor & may pose a risk to persons/children falling out when the window is open. This 2006 code requirement may not have been in force in this city until 2008 or later, as many cities do not adopt new codes (updated every three years) until 2-3 years after the "new" code is released. If concerned, you may consider checking with your local building/code enforcement department.  
2006 IRC - 613.2 - Window Sills: "In dwelling units, where the opening of an operable window is located more than 72 inches (1829mm) above the finished grade or surface below, the lowest part of the clear opening of the window shall be a minimum of 24 inches (610mm) above the finished floor of the room in which the window is located. Glazing between the floor and 24 inches (610mm) shall be fixed or have openings through which a 4-inch-diameter (102 mm) sphere cannot pass.

Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

**Report Identification 123 street; Allen, TX**

Exceptions:

1. Windows whose openings will not allow a 4-inch-diameter (102mm) sphere to pass through the Opening when the opening is in its largest opened position.
2. Openings that are provided with window guards that comply with ASTM F 2006 or F 2090”.

I NI NP D

**I. Stairways (Interior and Exterior)**

*Comments: All accessible stairways, regardless of age are compared to modern safety standards. Some “Improvements” and immediacy for repair or improvement may be subjective. Stairways & related component(s) are not inspected in an exhaustive manner, but rather for significant & obvious deficiencies or potential safety/hazard concerns in the opinion of the inspector, discovered during the limited time of inspection. If you are interested in more comprehensive stairway requirements, please refer to [http://inspectapedia.com/interiors/Stair\\_Codes.htm](http://inspectapedia.com/interiors/Stair_Codes.htm) & verify compliance independently.*

**Stairways: Deficient**

- ✚ Handrail was not present at the upper stair section as required at stairs/steps four (4) or more risers. IRC 311.5.6
- ✚ Spacing between rails would not meet modern requirements and Texas Real Estate Commission standards. Immediate repair needs are subjective. Current standards recommend the spacing of balcony, raised deck, and stair rails be close enough together that a 4” sphere could not pass through.

I NI NP D

**J. Fireplace / Chimney**

Fireplace:  Masonry:  Prefabricated.  Modern  Faux  Old / antiquated style  
Chase:  Masonry  Frame & Veneer  Frame & Brick/Stone  Not present  
Flue:  Masonry  Metal  Direct Vent  Undetermined  Not present  
Cap / Crown:  Mortar  Metal  Undetermined  Other  Not present  
Inspected at:  Ground / in home  Roof (limited)  Attic (limited)

*Comments: Inaccessible components are not inspected, and conditions remain undetermined. Inspection of inaccessible areas of flue / chimney interiors, fire screens / doors, mantels and surrounds is beyond the scope of this inspection. Code compliance and drafting characteristics are not determined by this inspection. Refer to the limitation information at the end of this document and consult your “Guide to Your Home Inspection” for more important related information.*

**NOTICE: The National Fire Protection Association (NFPA) requires a Level 2 inspection of fireplaces upon resale of the property. This should be performed by a professional chimney sweep who is a member of the Chimney Safety Institute of America and the National Chimney Sweep Guild. <http://www.ncsg.org/> <http://www.csia.org/HomeownerResources/ChimneySafetyInfo/tabid/112/Default.aspx> [http://www.sweep-masters.com/csia\\_visual\\_glossary.html](http://www.sweep-masters.com/csia_visual_glossary.html)**

**Fireplace & Hearth: Deficient**

- ✚ Fireplace interior is dirty and appeared to have some degree of creosote build-up. Cleaning is recommended.

**Damper: Deficient**

- ✚ A clamp was not present at the damper. Select Inspect recommends a clamp be installed on fireplaces with gas logs, to prevent gas and combustion product accumulation in the home. If such an improvement is made, an appropriate clamp should be installed to allow at least one inch opening for exhaust up through the chimney. This device is typically included with the gas log components, though many installers discard them rather than installing them as required by the manufacturers. Replacement clamps are available at fireplace stores.


**Fireplace Flue / Liner: Deficient**

- ✚ Fireplace interior is dirty and appeared to have some degree of creosote build-up. Cleaning is recommended.
- ✚ Portions of attic and chimney / chase components were inaccessible; conditions within remain undetermined.
- ✚ NOTE: Proper firestopping provisions were not confirmed, as the attic area surrounding the chase/flue was not readily accessible. Concealed chimney / chase portions of the flue were not readily accessible; conditions within remain undetermined.


**Chimney / Chase: Deficient**

- ✚ Chimney siding and or trim is decayed or otherwise damaged. Some materials should be repaired / replaced.

**Mortar Cap / Chase Cover: Inspected**  
**Gas Components: Inspected**  
 ▼ Operable



**Fabricated Fireplace**



**Masonry Fireplace**

I NI NP D

**K. Porches, Balconies, Decks, and Carports (Attached)**

*Comments: Refer to the limitation information at the end of this document and consult your "Guide to Your Home Inspection" for more important related information.*

I NI NP D

**L. Flatwork (Driveways, Sidewalks)**

*Comments: Refer to the limitation information at the end of this document and consult your "Guide to Your Home Inspection" for more important related information.*

I NI NP D

**M. Other (i.e. foliage, retaining walls, other structural related)**

*Comments:*

**Other: Inspected**

- ▼ Foliage touches the home at various perimeter locations. This is conducive to insect and moisture penetration. Foliage touching the home also creates a potential for damage to brick and siding areas. It is recommended to keep plants and shrubs trimmed at least 6 inches from the home, and to keep trees trimmed 5 feet from the home. Trimming of foliage is recommended. The heavier the coverage, the more relevant the need for trimming.  
 Though allowing shrubs to grow close to the home is not recommended, many people prefer the aesthetics of dense foliage over a less intrusive landscaping alternative. The decision to maintain your foliage may be subjective depending upon your landscaping preferences. Densely foliated areas are also obstructed and not readily accessible for inspection or discovery of wood destroying insects.
- ▼ Rodent evidence (trails, gnawing, feces) noted in the attic, exterior, & garage; rodents can gnaw on & damage electrical & HVAC component(s); recommend you arrange pest control maintenance
- ▼ Suspected Red-tip-photenias were noted at each side of the front porch. These large growing shrubs are aggressive and often take moisture from the soil that would otherwise benefit the foundation. It is not recommended to have this plant within thirty feet of the structure. This plant is frequently found rotting alive, and or infested with termites. Removal is strongly recommended.
- ▼ Large shrubs or trees touch the roof and or upper wall(s) at the northeast, & southeast. This is conducive to roof and wall damage. This is also conducive to insect and moisture penetration. It is recommended to keep plants and shrubs trimmed at least 6 inches from the home, and to keep trees trimmed 5 feet from the home. Trimming of foliage is recommended. The heavier the coverage, the more relevant the need for trimming. If roof damage was discovered, it is noted above in the "Roof Covering" section in this report.

- Tree(s) at the front & southeast have large roots growing near the ground surface toward the structure. This may be problematic currently, in the past, or future for the structure. Consult a specialist for options.

**II. ELECTRICAL SYSTEMS**

I NI NP D

**A. Service Entrance and Panels**

Service Type: & Meter Location:	Underground Side
Wire / Conductor Type:	Romex like (non-metallic sheathed cable)
Service wires at the main panel(s)	Copper _____
Maximum Amperage as indicated by the main breaker or panel labeling:	200 amps
Approximate Voltage at Service Panel, as indicated by wiring method:	120 / 240 Voltage is not measured
Breaker or fuse Panel Location(s):	Main- Garage Sub- Not Found or Not Present Other Sub- Not Found or Not Present

*Comments: Measuring amperage, voltage, or impedance is beyond the scope of this inspection. Alarm systems, low voltage systems, and remote controls are beyond the scope of this inspection and are not inspected, unless otherwise specifically noted in this section. The Texas Real Estate Commission requires comparison of all homes to current standards regarding AFCI protection. This means Texas inspectors must call out all locations that do not meet current standards as "deficient", without enabling a grandfathering clause. Codes and standards change often, and it is common that most homes (even many new homes) will not meet current TREC criteria. Obstructions are not unplugged or moved to access obstructed components. Appliances & corresponding OCPD are not referenced for compliance of manufacturer recommended current sizing. Refer to the limitation information at the end of this document and consult your "Guide to Your Home Inspection" for more important related information. Due to time & access limitations during a typical home inspection, the SoP for the electrical inspection portion of the TREC requirements is hereby departed from. Bonding/continuity, for example, is tested at major component(s) & systems only where accessible for an overall general assessment of conditions within the home/property.*

**Service Entry: Deficient**

- Electrical ground rod was not flush with the grade. "Electrical ground rod shall have at least 8' of length in contact with the soil and the upper end of the electrode must be flush with / below ground level unless above ground portion and grounding electrode conductor attachment is protected against physical damage. NEC 250-52 ( c ) ( 3)". This includes rod electrodes installed inside through concrete slabs.

Grounding rods are typically sold as 8 foot lengths; since the upper end of the rod has been left above grade, it is most likely not in contact with the soil for 8 feet as required. Since much of the rod is buried, the suspected condition cannot be confirmed nor discredited during this limited visual inspection. The grounding electrode connection is prone to physical damage and should be protected and secured to the structure or service riser. The rod should be covered with compacted soil or driven deeper into the soil. A grounding rod that protrudes from the ground / grade may also present an impalement hazard. Repair options are limited; and though this is technically incorrect, proper installation methods are rarely discovered, and frequently ignored by installers and city building code officials.

**Service Panels: Deficient**

- Air-conditioner condenser breaker(s) for the upstairs unit was larger (40amp) than the maximum allowed by the serial plate on the exterior air-conditioner unit (25amp). The condition deviates from manufacturer installation specifications and may void the manufacturer warranty. Consult an electrician and or the manufacturer of the condenser if concerned.
- One or more rooms and or required circuits did not have AFC (arc-fault-circuit) protection present as required in the 2009 NEC (National Electric Code). The Texas Real Estate Commission requires inspectors to report as Deficient the lack of Arc-Fault protection at circuits serving: family rooms, dining rooms, living rooms, parlors, libraries, dens, bedrooms, sunrooms, recreation rooms, closets, hallways, or similar rooms and areas. This basically includes all locations that are not required to be GFCI protected, should be AFCI protected according this standard. These are a valuable fire safety component and you should consider upgrading older breakers with this modern device; however, each breaker may cost \$40 or more, and there will usually be at least 10-15 needed for an average 2500-3000 sq foot home. Many homes built since 2008 already will have these, but only in the bedrooms. Many newer homes do not even meet this specific Texas Real Estate Commission requirement. More information regarding AFCI at <http://www.afcisafety.org/products.html>

Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

- ✦ The electrical disconnect panels for the air conditioner condenser unit(s) did not meet recommended clearance; the disconnect is considered a service panel and requires 30" lateral clearance and 36" front clearance from grade up to six feet in height. Disconnecting means shall be located within sight and readily accessible from the air conditioning or refrigeration equipment. Immediate repair needs may be subjective, and may be cost prohibitive pending your level of concern. This is mostly an access inconvenience for service personnel & not a safety hazard or urgent condition.

I NI NP D

**B. Branch Circuits- Connected Devices and Fixtures**

Branch Wire Seen at Panel(s):	Copper _____
-------------------------------	--------------

*Comments: Inspection of electrical outlets, switches, and fixtures is performed by testing a representative number of these components in accessible locations. In occupied homes, some electrical components are not accessible and not inspected due to personal items, furnishings, childproof covers, and other obstructions. Outlets, fixtures, switches, and smoke detection devices, if tested, are randomly inspected in a representative manner, where accessible. Refer to the limitation information at the end of this document and consult your "Guide to Your Home Inspection" for more important related information. GFCI (ground fault circuit interrupt) Devices*  
*The Texas Real Estate Commission requires comparison of all homes to current standards regarding GFCI location and operation. This means Texas inspectors must call out all locations that do not meet current standards as "deficient", without enabling a grandfathering clause. Codes and standards change often, and it is common that most homes will not meet current criteria.*

GFCI resets noted at:  Kitchen  Garage  Bath(s)  Exterior  Elec.Panel  NA/not found

**GFCI: Deficient**

- ✦ GFCI protection was not present or operable at all currently required locations. Texas Real Estate Commission standards require GFCI protection at all locations as described in the 2009 NEC (National Electric Code); these locations include: all kitchen counter top receptacles, bathroom, utility, laundry & wet bar sink receptacle(s) located within 6 feet of the outside edge of the sink, crawl space, outdoor locations, all garage locations. GFCI receptacle(s) at garage locations may be prone to tripping if it is on the same circuit as exterior receptacles; in the event the exterior receptacles are used for holiday lighting. If a refrigerator/freezer is on this circuit; food spoilage may occur in the event of a tripped circuit.
- ✦ **ADVISORY:** GFCI protection was not discovered at the garage ceiling (garage door operator receptacle(s)). Texas Real Estate Commission standards require GFCI protection at all locations as described in the 2009 NEC (National Electric Code);  
*"All 125 volt, single-phase, 15- or 20- ampere receptacles installed in garages & grade-level portions of unfinished accessory buildings used for storage or work areas shall have ground-fault circuit interrupter protection for personnel."* (IRC E3902)  
 In my opinion, it can be argued, that since this receptacle is not readily accessible (typically 8' or higher) that it would not be required to be ground-fault circuit interrupt protected; though the code appears to be vague on this issue. GFCI receptacle(s) at garage locations for refrigerators and garage door operators could be prone to nuisance tripping. If you sell the home in the future, a third-party inspector for the buyer may be required to report the condition as a deficiency.

**Outlets: Deficient**

- ✦ Damaged receptacles noted at the front porch, southwest bedroom at south wall, & garage.
- ✦ Exterior receptacle covers were inadequately sealed or otherwise deficient. Exterior junction boxes and fixtures require rain tight cover plates. NEC 370-15a.
- ✦ Damaged or missing outlet covers exist at the master closet & dining room northwest. This is a recommended, typically inexpensive repair.
- ✦ Receptacle(s) were loosely secured at the kitchen right of sink, family room west, master southwest, northwest bedroom at northeast. All outlets should be checked and tightened / repaired as needed before the home is reoccupied.
- ✦ **ADVISORY:** Many new homes have "tamper-resistant receptacles" as required by newer standards; this home did not have this newer safety feature at one or more locations.

*Residential & Commercial  
 Property Inspection*

- **ADVISORY:** Many new homes have modern “weather-resistant receptacles” as required by newer standards; this home did not have this newer safety feature at one or more exterior locations.



#### Lighting Fixtures: Deficient

- Fixtures were poorly secured at the northeast bedroom, dining room, & master bathroom left. Examination of all electrical components at this property should be performed by a qualified, professional tradesman; correction of any & all discovered deficiencies should subsequently be arranged and performed prior to closing.
- Fixture(s) at front porch & rear porch was/were not flush or appropriately secured. Excess “reveal” exists at electrical components. Fixtures and related covers shall be flush (*ideally within 1/8”*) and adequately secured to the finished wall/ceiling where mounted. This is to control potential fire-spread, and not necessarily for cosmetic reasons.
- Fan(s) at master & northeast bedroom were out of balance.
- Fixtures at the northeast bedroom & master should be properly mounted with mount covers flush to the ceiling/wall. NEC 410-4 & IRC E3903.9. Excess “reveal” exists at electrical components. Fixtures and related covers shall be flush (*ideally within 1/8”*) and adequately secured & fully sealed to the finished wall / ceiling where mounted.
- Kitchen, bedroom, bathroom, & family room bulbs or fixtures were not functioning as intended at the time of inspection. It is recommended that all fixtures be made operable prior to closing. This typically is corrected by replacing the light bulbs, though it is possible the fixture or other component may be amiss / deficient.


#### Switches: Deficient

- Arcing was seen or heard at dining room & study switches. This is potentially unsafe, and could be a fire hazard. Replacement of the switch is recommended.
- Switch covers were deficient at the attic & master closet. This is a safety concern. Repair is recommended and generally inexpensive.
- Master bedroom light switch was not functioning as intended-inconsistent

#### Smoke Detection Devices: Deficient

Smoke Alarms discovered at:     Bedroom(s)     Hallway(s)     Living area(s)     Other

- Smoke detection devices were not present or operable at bedrooms. Updating the system is recommended for fire safety.
- Current minimum recommendation is to have functional smoke detection devices located:
  1. In each bedroom / sleeping room,
  2. Outside each sleeping area (bedroom hallways) in the immediate vicinity of the sleeping rooms, and
  3. On each additional story of the dwelling, including basements but excluding crawl spaces and uninhabitable attics (in dwellings with split levels and without an intervening door between the levels, a smoke alarm installed on the upper level and the adjacent lower level shall suffice provided that the lower level is less than one full story below the upper level).



Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

**Report Identification 123 street; Allen, TX**

- ✦ It is recommended to test detectors monthly, change batteries annually, and to replace each detector at least once every ten years.
- ✦ Modern requirements dictate that smoke detector(s) should be hardwired to the electrical system with battery backup; this can be expensive on homes that do not have wiring in place for this purpose (generally older homes). Alarm(s) were not disassembled to determine if they were/were not hard wired. Consult an electrician if concerned.

**Other Accessible Electrical: Deficient**

- ✦ There are electrical wires at the attic(s) that are not properly secured and protected from damage by traffic. Where run across the top of floor joists, or run within 7 feet (2134mm) of floor joists across the face of rafters or studding, in attics & roof spaces that are provided with access, the cable shall be protected by substantial guard strips that are at least as high as the cable. Where such spaces are not provided with access by permanent stairs or ladders, protection shall only be required within 6 feet (1829mm) of the nearest edge of the attic entrance.  
Where cables are installed parallel to the sides of rafters, studs or floor joists, guard strips & running boards shall not be required.....  
Electrical wires/cables shall not be routed along walking surfaces or in any location prone to traffic damage. (E3702)
- ✦ Doorbell transformer was inadequately secured in the attic.
- ✦ What appeared to be an older doorbell or the alarm beeper was inadequately secured at the upstairs hall ceiling.
- ✦ NOTE: One or more of the recessed lights has insulation touching the canister. It is undetermined if the fixtures are rated for contact with insulation. As a precaution, you should have an electrician examine all fixtures for proper installation and clearance. Repairs should be made as necessary at that time.

**III. HEATING, VENTILATION, AND AIR-CONDITIONING SYSTEMS**

*This inspection is visual and only consists of readily accessible components and conditions at the time of inspection. Components and compartments are not disassembled; this is best done by an HVAC specialist. If you desire to have the HVAC system included in a Home Warranty, you should have a representative of that company examine components that may be covered, to determine compliance.*

**I NI NP D**

**A. Heating Equipment**

*Type:*       Forced Air     Gravity       Heat Pump      *Units:*  1  2  3  4+

*Age:*       Modern       Antiquated     Mixed Ages

*Energy Source(s):*     Natural Gas     Electricity     Propane       Other

*Power / Fuel Shut-Off:*     Beside unit     Manifold       Switch / breaker     Undetermined

*Comments: Stand alone-unvented gas units, and in wall gas units in bathrooms, bedrooms, or living areas are considered unsafe. Upgrading to safer modern heating equipment is recommended. If present, this type of heater is beyond the scope of this inspection and was not inspected. Heat exchangers and heating elements are typically inaccessible and are not inspected, unless otherwise noted. Refer to the limitation information at the end of this document and consult your "Guide to Your Home Inspection" for more important related information.*

**Heating: Deficient**

- ✦ The flue(s) does not meet listed clearance ratings from combustible materials, where penetrating the roof. The flue(s) are closer than recommended to wood/sheathing in the attic. It is recommended that flues be installed to manufacturer guidelines
- ✦ The system(s) are aged and should be serviced when other HVAC items are addressed by a professional HVAC technician. The system may be considered antiquated or nearing the end of useful lifespan by home warranty companies. Have your home warranty provider determine if the components will be acceptable for underwriting prior to closing.
- ✦ Rust and/or scale was present on the heat exchanger walls and/or at the burners. The systems should be fully serviced by an HVAC technician.



I NI NP D

   **B. Cooling Equipment**Type:  Forced Air  Evaporative  Window Unit(s)Fuel:  Electricity  Gas (uncommon in this area; beyond the scope of inspection)

Comments: System capacity, refrigerant type, and remaining life are undetermined. Unless otherwise noted, evaporators, blowers, and condensing units are not disassembled. The HVAC system has many inaccessible components. Full evaluation of refrigerant levels and leakage potentials, evaporators, compressors, blowers, and other inaccessible components requires an HVAC specialist. Refer to the limitation information at the end of this document and consult your "Guide to Your Home Inspection" for more important related information.

**Cooling: Deficient**

- Downstairs –interior 1989-90; exterior 1989; upstairs interior 1989-90 exterior 2003
- Corrosion exists at the downstairs evaporator cabinet and or interior. The condition should be examined and serviced by an HVAC technician.
- Prior auxiliary condensate line drainage or leakage is indicated by stains / corrosion at the auxiliary pans and drains. Refer to the seller's disclosure for possible information regarding this item. Ongoing leakage was not discovered. Conditions on days warmer than that of the inspection are undetermined.
- The downstairs air-conditioner system was cooling poorly @ <10° (less than standard 15°-22° differential from intake and output air). An HVAC specialist should examine and repair the system. Air conditioning output temperatures may indicate that the system is not working properly: perhaps the coil has become blocked solid with ice. Alternatively, high A/C outlet temperatures may be occurring, or even no cooling at all, due to other problems such as a loss of refrigerant. Part of this statement provided by www.inspect-ny.com
- The downstairs air-conditioner system was cooling poorly. The air-conditioner condenser / refrigerant line was not sweating during operation. This generally indicates low refrigerant level, though other conditions can cause this (this may simply be related to the dirty/compacted filters restricting airflow). An HVAC specialist should examine and repair the system.
- Deficient ducting suspected as implied by output differential of +-20° (both supply registers) in the master bedroom & bath.
- Condensate lines were not adequately insulated: Mildew and or accumulation of moisture was noted as present on or below the primary condensate line(s), and / or staining present at components below the traps. This may be prone to related moisture damage to attic flooring, insulation, drywall, and other attic / interior building components. Recommend addition of appropriate insulation past the trap and related components of the primary condensate line, as deemed necessary by an HVAC specialist. After that time, monitor the system / components periodically.
- Evaporator coils were dirty; servicing is recommended.
- Refrigerant insulation is amiss at various attic locations. Have this corrected with other HVAC repairs.
- A condenser is at or touching soil; corrosion was noted at the base of the unit. The unit should be 3 inches above grade to prevent premature corrosion of the base of the unit and lower interior components. Repair is recommended.
- The system(s) are aged and should be serviced when other HVAC items are addressed by a professional HVAC technician. The system may be considered antiquated or nearing the end of useful lifespan by home warranty companies. Have your home warranty provider determine if the components will be acceptable for underwriting prior to closing. The HVAC system has mixed ages of equipment. The system may be operable, though some older equipment may detract from the efficiency of the system.
- The primary condensate line termination was not discovered- commonly connected to plumbing vent or similar on older homes. It is undetermined if this drain has a self-sealing trap; if not, there may be a chance for sewer gas to enter the interior air stream. Recommend having this drain located and examined when other HVAC items are addressed

Select Inspect™  
Residential & Commercial  
Property Inspection

Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

**Report Identification 123 street; Allen, TX**

I NI NP D

**C. Duct System, Chases, and Vents**

Filter Type:  Disposable  Washable  Electronic  Other / Undetermined

Duct Type:  Flexible  Metal – Insulated  Concealed / Undetermined

Return Duct Location:  Attic  Between Levels or In-wall  Crawl space

Supply Duct Location:  Attic  Between Levels or In-wall  Crawl space

Filter Location(s):  At Unit(s)  Wall  Ceiling  Floor  Not Discovered

*Comments: Humidifiers, if present, are beyond the scope of this inspection and are not inspected. Humidifiers are considered conducive to mold growth. We recommend humidifiers not be used. Refer to the limitation information at the end of this document and consult your "Guide to Your Home Inspection" for more important related information.*

**Ducts, Vents, Chases, & Plenums: Deficient**

- Component connections were inadequately sealed; energy loss was detected.
- Duct manifolds/joints were amiss; deficient insulation, strapping, seal & or other conditions exist. Consult a licensed HVAC specialist for options.
- Crimped and or partially constricted ducting was noted. Tight strapping or sharp turns can restrict efficient airflow. Correction / improvement would be prudent.
- Ducts in various sections are inadequately secured. Repair would likely improve HVAC efficiency. You should contact an HVAC specialist to examine all related HVAC components and recommend improvement, repair or replacement options as needed.
- Moisture staining was noted around various registers. Recommended having your HVAC person examine this when other HVAC items are addressed.
- Fungus was present at air registers. This should be examined by an HVAC company, to determine if a related cause exists with the air-conditioner system. Mold testing was not performed by Select Inspect. Type of fungus remains undetermined.
- Rust was present at air registers. This should be examined by an HVAC company, to determine if a related cause exists with the air-conditioner system.
- Various air registers were dirty. Unclean air registers often indicate air leakage conditions in the ducting connections. Be advised that duct cleaning personnel often cause damage to flexible air ducting during attempts to clean them.
- The plenum(s) was discovered as dirty; cleaning/maintenance is recommended.

**Air Filter(s): Deficient**

- Downstairs filter is unclean.

**Thermostat(s): Deficient**

- Downstairs thermostat(s) was inconsistent; appeared to be short cycling, & turned on at one point even though it was in the off position.
- Prior to departure Thermostats were reset to "off-as found on arrival" by the inspector.

**IV. PLUMBING SYSTEM**

I NI NP D

**A. Water Supply System and Fixtures**

Supply Pipe (visible):  Copper  Plastic; PEX, or similar  Polybutylene  Other / undetermined

Water Meter Location:  Front  Side  Rear  Alley  Undetermined / Not found

Water Shut-Off:  Exterior North  Garage  Interior room / closet  Undetermined

Waste Pipe (visible):  Plastic  Metal  Drain pipe: Undetermined on slab homes

Vent Pipe (visible):  Plastic  Metal

Static water pressure at the time of inspection was approx. 84-87 psi; 40-80 psi is an acceptable range

*Comments: Fixtures are not filled to capacity. Inaccessible components below grade, below, or behind cabinets and walls, and behind or below bathtubs, showers, or sinks are not inspected; conditions and type of material remain undetermined. Personal items are not moved or removed from sink, bathtub, shower, or toilet areas, and these items may obstruct access and visibility. We cannot guarantee that all potential or inaccessible leakage conditions will be discovered. Refer to the limitation information at the end of this document and consult your "Guide to Your Home Inspection" for more important related information.*

Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

**Report Identification 123 street; Allen, TX**

**Plumbing Supply: Deficient**

- The secondary water shut off valve components were soil covered at the front right garden. The valve and or handle were inaccessible and conditions remain undetermined. Repair (uncovering) of the shut off is recommended. Shut-off valve did not have recommended 3" clearance from soil.
- Water pressure was 84-87psi; higher than the recommended 40-80 psi. A pressure reducing valve was not discovered. When a pressure reducing valve is installed, your plumber should install an expansion tank at the water heater. Related information can be found at [http://www.watts.com/pro/divisions/watersafety\\_flowcontrol/learnabout/learnabout\\_wprv.asp](http://www.watts.com/pro/divisions/watersafety_flowcontrol/learnabout/learnabout_wprv.asp)

**Sinks: Deficient**

- Master right sink drips when in the off position.
- Drainstops were not functioning as intended at the powder bath, master & upstairs bathroom.
- Corrosion/sediment exists at various fixtures including master bathroom

**Toilets / Bidets: Deficient**

- Powder bath toilet(s) was inadequately secured at the floor. Correction / improvement would be prudent.
- Master toilet leaks below the tank; water was turned off at the toilet after testing.

**Bathtubs: Deficient**

- The hot and cold valves are reversed at the master if viewed from within the bathtub(s); from the user's perspective, hot should be on the left & cold on the right. I personally would use the controls & fill it before getting in & though it is debatable, there are some inspectors who will call this deficient; Immediate corrective needs were not discovered.
- Unusual random knocking sound was heard when operating the upstairs bathtub(s); possibly water hammer.
- The upstairs bathtub(s) have chipped material. The condition was minor at the time of inspection, though over time, corrosion may occur. Patching is recommended.

**Showers: Deficient**

- Master shower door weather-stripping components were amiss/deficient. Repair is recommended.
- Fungus was noted at the master shower(s). This can cause damage to and eventual failure of grout/caulking. Recommend cleaning and routine maintenance.

**Exterior Faucets: Inspected(Attached Only; unless otherwise noted)****Utility Connections: Not Inspected**

- It is beyond the scope of this inspection to operate laundry plumbing connections and laundry appliances. These fixtures are visually inspected only when accessible. Some conditions remain undetermined. If present, laundry equipment is not moved or inspected.

I NI NP D

   **B. Drains, Wastes, Vents**

*Comments: Underground and inaccessible components are not inspected; conditions remain undetermined. Refer to the limitation information at the end of this document and consult your "Guide to Your Home Inspection" for more important related information.*

**Drains, Wastes, Vents: Deficient**

- Slow drains were noted at the upstairs bathtub(s) & master left sink. Correction / improvement would be prudent.

**DWV: Not Inspected**

- The home is vacant and it is possible that drain lines have dried. This can cause loose sludge accumulation and congestion down the lines shortly after the home is re-occupied, when water fixtures are put back in use. If this occurs, (typically within 5 months) it is possible for sewage to back-up into the home through plumbing fixtures. The immediacy of calling a plumber is a subjective decision. OPTIONS: 1) If you are concerned or want to alleviate risk of this possibility, then having the drains serviced prior to move in would be prudent. 2) You can monitor the drains, and contact a plumber if / when congestion is discovered. 3) If there are other plumbing conditions noted in this report that you plan to have improved / repaired, then it may be cost effective to have this possible condition evaluated further at that time.
- NOTE:Sub grade, in-wall, and some attic / crawl space plumbing components were not accessible; conditions remain undetermined.
- The potential for sub grade plumbing leaks and failure increase as a home ages. If you are concerned or notice problems, consult a specialist to examine the condition of buried pipes.

I NI NP D

**C. Water Heating Equipment**

Energy Source:  Gas  Electric  LP Capacity: 50 gallon; ; ;

Number of units:  1  2  3 or more PRV(s)/TPRV(s): Manually Tested  Y  N

Power / Fuel Shut-Off:  Beside unit  Switch or breaker  Inaccessible./ undetermined

*Comments: The inspection does not determine remaining life expectancy, condition of interior or inaccessible components. The inspection cannot determine if bacteria or corrosion exists at the interior or in inaccessible areas. Average life of a water heater is around 8-12 years; some last longer, some fail sooner. Refer to the limitation information at the end of this document and consult your "Guide to Your Home Inspection" for more important related information.*

**Water Heater: Deficient**

- The flue(s) was not adequately supported/strapped. IRC M1801.7
- Most of the water heater flue was concealed within wall/chase/attic areas and was not readily accessible for inspection. It is undetermined as to the condition, and adequacy of securing and clearances of concealed components
- The temperature-pressure-relief valve is improperly routed uphill. This will not allow proper gravity draining, and repair is recommended.
- The temperature-pressure-relief was not tested. The water heater(s) is over three years old- per manufacturer label. It is recommended to have the temperature-pressure-relief tested annually, and have the temperature-pressure-relief removed and visually inspected every three years or sooner. Most manufacturers also recommend draining / flushing the water heater at least once annually. The unit was producing hot water and appeared generally operable at the time of inspection, though it does not appear to have a documented service history. Recommend having the unit(s) examined and serviced by a plumber, or at the very least, you should realize that it does not likely meet manufacturer's guidelines for routine maintenance. Average life of a water heater is 10-12 years; Serial plate codes on the water heater imply the unit(s) were built in 2006.
- Advisory: It is recommended to read and follow all manufacturer's labels, warnings, and maintenance information. Following these guidelines will provide for safer conditions, and can extend the life of the unit and its components.

I NI NP D

**D. Hydro-Massage Therapy Equipment**

*Comments: This section pertains to individual systems, not part of a swimming pool. Some areas and components are inaccessible by design and location. Conditions of inaccessible components remain undetermined. Refer to the limitation information at the end of this document and consult your "Guide to Your Home Inspection" for more important related information.*

**V. APPLIANCES**

Built-In Appliances, if present and inspected, are inspected in normal modes by using installed standard manufacturer provided controls only, where present & deemed safe to do so by the inspector. Built-In Appliances and related components are examined for noticeable deficiencies of operation, visible damage, and obvious installation issues. Built-In Appliances and related components are not dismantled or moved, unless otherwise noted specifically in this report. Appliances that are not built-in are not inspected unless otherwise noted specifically in this report. Consult your "Guide to Your Home Inspection" and the limitations section at the end of this document for more important information

I NI NP D

**A. Dishwasher**

*Comments: Dishwashers are not "approved" by the inspector for compliance with current local code regarding anti-siphon protection. Most manufacturers route the drain in an anti-siphon manner at the side of the dishwasher; this condition cannot often be determined when the unit is installed. Sink-top anti-siphon devices and other dishwasher drain connections are prone to leakage, congestion, and wear; these should be monitored periodically for leaks and damaged components. Conditions of inaccessible components and lifespan remain undetermined.*

**Dishwasher: Deficient**

- The anti-siphon device at the dishwasher was not properly routed for gravity drainage to the disposal/drain. Correction is recommended & usually simple.
- Advisory: When the home is / has been vacant for more than a few weeks, please remember to run some hot water through kitchen / bathroom faucets prior to operating the dishwasher when you first move in. This may seem strange, but there is a chance of hydrogen building up in a water heater that has been heating, but not in regular use; this can sometimes cause an explosion when the dishwasher is

Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

operated before other water fixtures. In some cases, it is possible for hydrogen to enter and subsequently ignite in the dishwasher when the timer control engages. Running hot water for 4-8 minutes simultaneously at fixtures (when you first move in) should release any potential hydrogen accumulation in the system. Related article can be found at:

<http://www.cdc.gov/elcosh/docs/d0400/d000435/d000435.html>.

I NI NP D

### B. Food Waste Disposer

*Comments:*

#### Disposal: Deficient

- ✦ The unit was corroded at the interior & exterior canister.
- ✦ The clamp to secure the electrical wires where they enter the disposal unit was amiss / deficient. Repair is recommended.

I NI NP D

*Vent Type:*

### C. Range Exhaust Vent

Recirculating  Exterior  Down-draft  N/A - Not Present  Undetermined

*Comments:*

I NI NP D

### D. Ranges, Cooktops, and Ovens

*Comments: Ranges, stoves, ovens etc are not moved or dismantled in any way unless otherwise specifically noted in this report. Presence of and condition of inaccessible components remain undetermined. Obstruction limitations often include method of installation, stored items, walls, and other components. Condition and type of gas or electrical supply components including gas lines and valves, electrical wires, connections, junction boxes, and conduit are mostly inaccessible; and only readily accessible components if seen will be inspected. Gas valves if present and discovered are not operated unless otherwise specifically noted in this report. Some conditions will be undiscovered and unreported.*

#### Range/Cooktop: Inspected

*Range/Cooktop-Energy Source:*  Natural Gas  Electric  LP (propane)

#### Oven: Inspected

*OVEN- Energy Source:*  Natural Gas  Electric  LP (propane)

I NI NP D

### E. Microwave Oven

*Comments: Pertains to built-in equipment only. Radiation testing is beyond the scope of this inspection.*

I NI NP D

### F. Trash Compactor

*Comments: Trash compactors have a high repair frequency, and should be kept cleaned and well maintained. It is recommended that you not crush glass or other fragile material in a compactor.*

I NI NP D

### G. Mechanical Exhaust Vents and Bathroom Heaters (includes utility room fan if present)

*Comments: Many attic and in-wall components are inaccessible. Condition of ducting (if present) in non-readily accessible areas and location / appropriateness of vent termination is not determined or guaranteed.*

#### Exhaust Vent / Heater: Deficient

- ✦ Some / all bathroom /laundry exhaust fans appear to vent to the attic. Vent termination within the attic, at passive roof vents, or at eave vents does not meet most manufacturer guidelines. Current standards require venting of bathroom and utility room exhaust fully to the exterior. (IRC M1507). Texas Real Estate Commission considers this deficient, even on older homes. Related technical information can be found at: <http://www.toolbase.org/PDF/DesignGuides/spotventilation1.pdf>

Residential & Commercial  
Property Inspection

Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

Report Identification 123 street; Allen, TX

I NI NP D

**H. Garage Door Operator(s)**

*Comments:*

**Garage Door Operator(s): Deficient**

- Lock device is present at one or more garage doors. Texas Real Estate Commission considers this deficient when a garage door operator is connected. Repair needs are subjective.
- Technically the pull cord should be no higher than 6 feet above the floor; one or more manual release cords were higher than 6 feet from the garage floor. Immediate corrective/improvement needs may be subjective.
- NOTE: Current standards require motion (auto-reverse) sensors on modern garage door operator systems. One or more related locations at this property did not have this modern safety feature. This feature will be included on a modern opener when such is installed in the future. Immediate repair needs are subjective.

I NI NP D

**I. Door Bell and Chimes**

*Comments:*

**Door Bell: Deficient**

- The chime was inoperable/in audible at the time of inspection. \*device chimed when manually contacting the conductors at the transformer in the attic, though the device was inoperable when using the button at the front entry.

I NI NP D

**J. Dryer Vents**

*Comments: This inspection is limited to accessible and visible sections and components only. This inspection does not determine length, code compliance, or presence of obstructions or damage to inaccessible components. <http://www.csa.org/HomeownerResources/ClothesDryerVentSafetyTips/tabid/113/Default.aspx>*

Vent Routing:

Wall  Attic / Roof  Crawl space  Obstructed  Undetermined

**Dryer Vent: Not Inspected**

- The vent is partially routed in not readily accessible areas. The complete interior condition of the vent is undetermined, and should be checked for cleaning needs before new appliances are connected.

**VI. OPTIONAL SYSTEMS**

Optional Systems include Sprinkler systems, Pools / Spas / Hot-tubs, Outbuildings, Outdoor Grills, Gas Lines, Septic systems, Water Wells, Security systems, Fire Control systems. Unless otherwise noted specifically in this report, these and any other systems and components are Not Inspected.

I NI NP D

**A. Lawn and Garden Sprinkler Systems**

Controls:

Electronic  Programmable  Manual Zones Wired: 6

Anti-Siphon:

Near Curb  Near home  Front  Side  Rear  Undetermined

*Comments: Refer to the limitation information at the end of this document and consult your "Guide to Your Home Inspection" for more important related information.*

**Irrigation: Deficient**

- Rain sensor was not discovered. Texas Real Estate Commission considers this a deficiency, although most older systems require retro-fitting for this type device.
- Shut-off-valves require 3" clearance from soil; the components at this system were at, near, or below soil.
- Heads spray fencing. This can contribute to premature decay/failure of the fencing & promote conducive conditions for wood destroying insects. Recommend adjusting the irrigation heads to not/minimally spray wood components & the home.
- Heads improperly spray the home at various perimeter locations This can be conducive to decay and or mortar erosion. Improperly adjusted sprinkler heads can contribute to foundation movement and conducive conditions. Adjusting the spray pattern, radius, and or direction is recommended.
- Coverage was amiss at the west-southwest, east, south. Unworkmanlike installation, few heads- spread out with inadequate overlapping.
- NOTE: Irrigation control was powered at a GFCI receptacle. This generally works, though as a future improvement, or with other electrical repairs, you may consider placing this on a non-GFCI (standard

110) receptacle, to avoid tripping and potential need for reprogramming of the timer. Immediate repair needs are subjective; this is an advisory and not a repair statement.

- Irrigation heads/risers at various perimeter locations were higher than recommended; these should remain low to ground to offer water below shrubs for the foundation; this is a common error, & can generally be corrected by replacing the risers with shorter component(s).
- One or more heads spray well onto neighboring property or public areas. The overspray is wasteful, and can often be reduced by decreasing the radius of projection- most heads have a small screw atop the head that can be turned to increase/decrease the spray radius size. Recommend adjusting and monitoring.
- Trajectory should be adjusted at the rear to allow better coverage as intended.

I NI NP D

**C. Outbuildings**

Comments: The integrity and remaining life expectancy of the building is not determined. External storage buildings if noted, are very briefly observed for obvious issues only, and are not included with the normal inspection of the property unless prearranged. Comments, unless otherwise stated, do not reflect the full aspect or condition of outdoor buildings and their components, if such buildings are present.

I NI NP D

**E. Gas Supply Systems**

Gas Meter location:     Front     Side     Rear     Garage     Undetermined     N/A

Gas Shut-Off:         Meter     Attic     Garage     Service Riser     Unknown     N/A

Comments: Underground and inaccessible components are not inspected; conditions remain undetermined. Refer to the limitation information at the end of this document and consult your "Guide to Your Home Inspection" for more important related information.


**Accessible Gas Components: Deficient**

- Piping in the attic was inadequately secured & inadequately protected from traffic.
- NOTE: a gas leak test was not done due to preexisting conditions or obstructions of the furnace(s) causing probable inability to readily reignite the pilot(s). Significant issues were not found or observed concerning this item at the time of inspection.
- NOTE: Sediment trap(s) were not seen/not present at the gas branch between the shut-off valve and furnace, stove, and or water heating appliance(s). Historically natural gas in this region is clean and does not require a sediment trap per the supplier. However, many local (city) code departments are currently requiring sediment traps as specified in the code (IRC G2419.4 (UPC408.4)) and the supplier cannot control what happens after the meter. Immediate repair needs may be subjective; You should have a licensed plumber examine the issue(s) and recommend improvement, repair, or replacement options if you are concerned. This is not required at illumination devices, clothes dryers, outdoor grills.

**Underground / Inaccessible Gas Components: Not Inspected**

- Conditions of inaccessible gas components including but not limited to: buried, in-wall, behind or beneath appliances or components, attic and crawl space locations, or enclosed within any component or appliance are not inspected and remain undetermined. If you have concern or if the gas system or any gas related components are over 10 years old, it is recommended to have a specialized comprehensive gas system examination of the property, prior to closing.

This is the end of the report findings. Important inspection information is continued on the following pages and in the "Guide to Your Home Inspection"; please take time to read them in their entirety. Thank you for your business; Select Inspect Property Consultants LLC- 214-770-6954.



## LIMITATIONS, EXPLANATIONS, & DEFINITIONS

Thank you for choosing Select Inspect. Your business and confidence in our service is greatly appreciated. These final pages are an integral part of the Select Inspect Report; it is important that you read the report in its entirety before purchasing the home.

### OP-I, TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING RECOGNIZED HAZARDS:

"Each year in Texas, people are injured and property losses occur from: improperly installed water heaters in garages, faulty temperature and pressure relief valves on water heaters, and improperly installed (or the lack of) ground fault circuit protection for electrical receptacles in garages, outdoors, bathrooms and kitchen sink areas. In recognition of the studies and recommendations from the U.S. Consumer Products Safety Commission (U.S. CPSC), the Texas Real Estate Commission (TREC) has adopted a rule requiring licensed inspectors to report the above listed hazardous conditions as "deficient" when performing an inspection for a buyer or seller. These conditions may not be a building code violation in a particular city or locale, or may be "grandfathered" because they were present prior to the adoption of city ordinances prohibiting such conditions. TREC has considered the potential for injury or property loss to be significant enough to warrant this notice. The effect of this rule is not to mandate these conditions be remedied, but rather to insure that the consumer be made aware of these significant hazards when revealed by inspection. Once notified, a buyer can decide whether or not to add them to the prioritized list of repairs that is typically provided to a seller under a Texas Earnest Money Contract and the Property Condition Addendum. The decision to correct the hazard is left to the parties involved in the transaction."

#### General Limitations:

If a concern arises, regarding this report, you must notify Select Inspect prior to purchasing the property, and allow us to reinspect the property and or components of concern prior to any changes being made to the components or condition of concern. Otherwise, all claims for damages or costs incurred from those complaints and related improvements, modification or repair are waived by the client.

Select Inspect makes no representation except what is specifically contained within this document and the Select Inspect Inspection Contract. This report and the Select Inspect Inspection Contract are the sole and only agreement between Select Inspect and the client, and supersedes any prior written, verbal, or implied agreements between the client and Select Inspect regarding content within the Select Inspect Property Report, and Inspection Contract.

By acceptance of and or reliance upon information in this report, the client agrees to the conditions of the contract, even when the client fails to sign the contract. Client agrees that any potential controversy or claim between the client and Select Inspect shall in good faith be brought to mediation by a third party, having no interest in this case, before filing suit for any amount of damages. By acceptance of and or reliance upon information in this report, the client agrees that any damages resulting from breach of this contract or report are limited to the fee charged to the client by Select Inspect for this inspection service.

By accepting and relying on the information within these documents, the client expressly agrees to all agreements and limitations herein.

The inspection is cursory and limited. The findings represent observed conditions at the property on the day and time of the inspection. This is not a fully comprehensive inspection, and there may be items or conditions that are not discovered or not reported. Though reference to current standards or the word "code" may be noted in portions of this document, Select Inspect does not inspect the property for compliance to prior, current, or future "code" regulations. The service attempts to reduce risk, but cannot and will not eliminate risk of purchasing any property. Select Inspect does not warrant or guarantee that all conditions will be discovered or reported. Protection regarding errors and omissions are not stated nor implied. Comprehensive inspections of components and areas of the property can be arranged for through specialists in each given field. The inspector does not offer opinions regarding value or whether the property should be purchased. It is strongly recommended to obtain receipts, reports, and warranty information for prior repairs, and receipts, reports, and warranty information for repairs made due to discoveries during this inspection.

#### Foundation / Structure:

The inspector is not an engineer, and is not required to provide engineering decisions or to specify repair recommendations. The inspector is required to render an opinion on the present condition of the foundation. Time, landscaping modifications, seasonal changes, and moisture conditions will affect the foundation and structure to some degree. The inspector cannot determine the future performance of the foundation or structure. The inspector cannot and does not determine the quality of or appropriateness of reinforcing steel or post tension cable placement and conditions of sleeves, cables, or reinforcing steel within the foundation form. The inspector does not determine if post tension cables are under appropriate tension. Inspector does not determine condition / location of routing in the foundation, or the condition of reinforcing steel / post tension clamps that are covered or otherwise inaccessible. These tests can be done with special equipment, by specialists. These tests are usually expensive, and if issues are found, the correction may damage the foundation, or may not be cost effective.

The crawl space below a pier and beam home has areas that are likely obstructed and or at least partially inaccessible. It is extremely rare that a crawl space will be fully accessible. It should be understood that all conditions within a crawl space will not be discovered. For safety reasons, the inspector is not required to enter a crawl space with an opening of less than 18" X 24", and or crawl space areas having a clearance of less than 18" between the earth and the bottom of the framing. The inspector is not required to enter and inspect crawl space areas that he determines as unsafe. This typically includes conditions such as electrical wiring on the soil or otherwise unsafe in condition obstructing access; wet soils or moldy areas; and the presence or suspected presence of rodents, reptiles, or animals. Floor coverings and stored items at the interior obstruct occupied and vacant homes. Areas within and beneath walls are inaccessible. Conditions of structural components within wall voids, components obstructed by storage or floor coverings, or otherwise inaccessible remain undetermined.

#### Drainage:

Grading and drainage conditions are noted regarding visible and present conditions on the day of and at the time of inspection. Many North Texas areas contain highly expansive clay soils. These soils are largely responsible for foundation movement. Clay soils should be consistently moist; not too wet and not too dry; to help maintain a stable foundation. Soils / grade should slope away from the home. Grading that slopes toward the home is conducive to foundation movement and insect activity. Some foundation movement and settling is common and expected. By maintaining drainage and moisture levels around and below the home, you can reduce the risk of excessive or significant foundation movement, moisture intrusion, and fungal issues.

It is important to keep the grade level at least 4-6 inches below the bottom of brick / stone. Soil should be at least 6-8 inches below wood or wood-based siding / trim. Siding should be at least one inch minimum above concrete slabs at patio / porch areas. This would allow the edges of the foundation to be visible for inspection of termites and moisture intrusion conditions. High soil and low siding at foundation joints are conducive to moisture intrusion, rot, and termites. If soil levels are adjusted, be sure not to create poor drainage conditions.

Impact of run-off from the inspected property on neighboring homes and visa versa remains undetermined. Condition, slope, capacity, and termination of sub grade gutter or other drain components remains undetermined. Histories of flooding, moisture intrusion, water tables, and elevations are beyond the scope of this inspection, and remain undetermined. Unless noted in the report; the drainage histories, current and future drainage capabilities, past, present, and future mold or fungal issues in crawl space, basement, and sub-grade living, and inaccessible areas are undetermined. Future performance of surface and sub-grade drainage characteristics in weather conditions other than those ongoing at the time of inspection, remain undetermined. Specialty services including flood plain analysis, sub grade water table surveys, and microbiological tests are available from other companies that specialize in those fields. If you have concerns and or desire to alleviate all risk regarding these potential conditions, you should contract a specialist for full evaluation of the property regarding that concern. If obvious problems of nearby foliage are seen, the conditions may be noted in the report. However, future or potential impact of foliage to the property and structures and related issues are undetermined, and any comment regarding such is partial in context. The current or potential impact of large trees around the home is undetermined. If you are concerned with location or condition of trees (of any size) at the property, you should consult a professional landscaping arborist for options.

#### Roof / Attic:

Roof and attic areas are observed in a cursory manner. Roofs deemed unsafe for access by the inspector will be observed through binoculars at ground level, and or from a ladder placed at the eaves. The inspector is required to describe the method used to inspect the roof. The inspector is looking for obvious immediate repair needs, that may allow moisture intrusion, structural, or safety concerns. The inspection does not report regarding installation with manufacturer specifications, code (current or

Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

**Report Identification 123 street; Allen, TX**

at the time of installation), or manufacturing defects. This is not a "hail" inspection and should not be used as a hail report. If you are concerned with hail damage or insurability, you should have your insurance company physically examine the roof prior to closing. You should read your insurance policy and make sure you understand all of the policy limitations. All histories of hail may not be visible, and will not be reported. Hail evidence may be noted in the report, though all hail evidence does not necessarily mean hail damage and need for repair. The inspector will observe the roof for obvious flashing defects and improper installation methods. Many areas of flashing are covered by other materials by nature of installation and design; therefore, all potential issues at flashed areas and components will not be found or reported. Lifespan, brand / quality of material, number of roofing layers, presence of felt in all appropriate locations, and insurability are not determined. Structural capacity and integrity of brick or wood supported chimneys is undetermined. Comments may be made regarding obvious or suspected deficiency conditions at the time of inspection; further comprehensive examination and repairs should be made by a framing and or mortar specialist.

The attic areas will be accessed whenever deemed safe by the inspector. The inspector is not required to enter attic areas with height less than 4' clear headroom and those without decking / flooring; these areas are considered inaccessible and unsafe. The inspector may comment on comparison of modern framing standards to older framing, though he does not calculate spans, loads, adequacy, or code compliance (past or present). Attic components are observed for signs or evidence of moisture intrusion, safety issues, and damage or failure. It is common for framing to deflect to some degree, and some new inspectors will consider all older homes deficient. Select Inspect inspectors will form an opinion based on the performance of the structure. Slight deflection, old style framing, and or prior leakage in limited areas do not necessarily warrant or require expensive repair. Our concern is "how has the structure / component performed over its apparent lifespan?" The inspector is required to only comment on prior moisture intrusion evidence in attic areas and discovered interior areas and make a judgment decision whether or not it is a deficiency in the inspector's professional opinion. If moisture conditions found in the home appear significant or ongoing, the inspector will note the condition(s) as deficient. Ventilation provisions frequently do not meet current / modern standards. The inspector does not calculate area and appropriateness of ventilation location and adequacy. Ventilation provisions between insulation at vaulted ceilings and roof decking remain undetermined.

**Insulation:**

Insulation is observed from accessible attic areas. Condition in wall voids and other inaccessible locations remain undetermined. Code compliance, material brand or type, R-value, and efficiency are not determined. Identification of asbestos and fire / health risks are not determined or reported. Vapor barrier presence, adequacy, and appropriateness of installation are not determined or reported, unless obvious defects or conditions are found and noted in the inspection report.

**Walls** (interior and exterior):

Cosmetic flaws, conditions, or defects are not inspected or reported. Exterior Insulated Finish Systems (EIFS) synthetic stucco are not comprehensively inspected. The presence of or history of mold or moisture intrusion is not inspected. Adequacy of flashing installation, and methods used is undetermined. All homes with EIFS or other synthetic stucco should be inspected by a synthetic stucco specialist prior to closing. Appropriateness, quality, durability, and moisture resistance of brick, mortar, and siding materials are not determined. Some brands of "hard-board" type siding and trim have been under litigation for premature failure, rot, and fungal issues. These pressed board type materials are more prone to moisture / rot damage, and should be kept well caulked and painted to reduce risk. Modern cementitious materials are more durable, less problematic, and more expensive, though they do require some routine maintenance. **Chinese Drywall links** & related information:

<http://www.cpssc.gov/info/drywall/index.html> & <http://www.doh.state.fl.us/environment/community/indoor-airr/casedefinition.html#presence>

**Windows & Doors:**

Windows and doors are randomly inspected for functionality and moisture intrusion where accessible. Though some comments regarding presence of safety glass may be made, the inspector does not test or compare fenestrations and glass to current standard or code. Some failed double-pane windows and glass may be mentioned, though all conditions may not be found. Conditions prohibiting the findings of all moisture intrusion, deficiencies, and failed seal conditions include: furniture, poor lighting, window treatments, stored items, shrubbery, and other stored items. Some subtle seal failures may go undetected. Cosmetic deficiencies are not inspected and not reported. It is recommended to have all key locked door hardware re-keyed or replaced. Storm windows are not operated.

**Fireplace:**

Fireplaces are inspected at visible components only. Frequently inaccessible components are: flues, chases, roof side chimneys and caps, and enclosed areas behind logs and prefabricated panels. Drafting characteristics are not determined. Component clearance from combustibles may be noted, when manufacturer labeling is readily accessible, and deficiencies are obvious. Installation to code or manufacturer guidelines is not determined; any comment relating to such is incomplete and partial in context. If concerns or suspect installation methods or components are found, you should have a fireplace specialist examine the fireplace(s) and repair any issues.

**Electrical:**

Electrical components are tested with normal controls. Outlets and switches are randomly tested at accessible locations only. Furniture, child-proof covers or other obstructions frequently prohibit access to all outlets. Regarding presence and location of GFCI protection: the inspector is required by the Texas Real Estate Commission to compare all homes to current electrical code. Most pre-existing homes will not meet this requirement, and replacement of non-GFCI circuits with GFCI circuits is a good safety recommendation, though updating the home is a subjective decision. Many consider this an improvement rather than a repair. Voltage and amperage ratings are described by observing accessible labeling at accessible service components. Voltage and amperage are not measured. Low voltage systems are not inspected. Landscape lighting is not operated. Comments regarding low voltage and landscape systems are partial in context. Underground and inaccessible wiring, conduit, or other electrical components are not inspected, and conditions of inaccessible components remain undetermined. Circuits are not traced; the inspector does not determine adequacy or correctness of breaker labeling. Electricity can be deadly; Select Inspect cannot guarantee the home or property to be free from electrical hazards. The inspection does not determine insurability of the property. Any and all electrical concerns should be evaluated and repaired by a master electrician. If an electrician is contracted to work in the home, it is recommended that the electrician examine all electrical components / systems at the property and repair all discovered deficiencies prior to closing.

**Heat & Air Systems** (HVAC):

HVAC systems are not dismantled and some interior conditions may go undiscovered. Only readily accessible components are inspected. Only readily accessible panels are removed for inspection. Heat exchangers are not opened or fully inspected. Full evaluation of heat exchangers requires an HVAC specialist. Humidifiers, dehumidifiers, electronic air filters, and solar space heaters are not inspected. The inspector does not determine supply adequacy or distribution balance. The HVAC systems are operated with normal controls (thermostats), when possible. Heat pumps are not operated in heat mode when outdoor temperature is 80 degrees or higher. Air-conditioner units are not operated when outdoor temperature is below 60 degrees. Air quality is undetermined. Mold / fungal presence is undetermined in inaccessible areas and components. Evaporators are not usually disassembled. If the evaporator does not have a history of professional cleaning over the past 4-5 years, professional cleaning is highly recommended. If one or more HVAC components are noted deficient, and repair is recommended, you should have a licensed HVAC company examine the entire system(s) and repair all discovered deficiencies before closing.

**Plumbing:**

Laundry appliances and connections are not inspected. Water conditioning / filtration systems; solar water heating equipment; fire sprinkler systems; private waste disposal systems (septic); water wells, well pumps, and water storage equipment; and quantity (pressure), or quality of water supply are not inspected. Sometimes plumbing drains will dry out during vacancy. If this occurs, shortly after re-occupation, there may be a build-up and potential blockage of residual sludge. This can affect drainage and venting. If the home has been vacant for more than a few months, you should either 1) have the lines checked and cleaned, or 2) monitor the drain system for issues. If issues are discovered, cleaning by a licensed plumber will be necessary. Inaccessible flues, drains, supply, gas piping, and related components are not inspected. The condition of all sub grade components remains undetermined. Water heaters are operated in normal modes only, while checking hot water at accessible plumbing fixtures during the inspection. Insurability, remaining life, condition of interior components, and absence of bacteria or corrosion at the interior of the water heater is not warranted or determined. Safety, pressure, and shut-off valves are visually inspected only when accessible, and are not operated. The presence or absence of bacteria or corrosion within inaccessible piping, fixture, and appliance components is undetermined.

Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

**Report Identification 123 street; Allen, TX**

**Appliances:**

Unless otherwise noted, refrigerators, ice-makers, wine coolers, freezers, and similar appliances are not inspected. Appliances that are not inspected are not opened or moved. Refrigeration equipment should not be on GFCI circuits. If the circuit trips, the unit(s) may not restart, and subsequent food spoilage or damage may occur. If a refrigeration appliance is observed on a potential or obvious GFCI circuit, all suspected portions of that circuit will not be GFCI tested. For example: if a refrigerator appears to be on a suspected GFCI circuit in the garage, the garage outlets, and exterior outlets are typically on the same circuit, and will not be GFCI tested. If inspected, dishwashers, disposals, compactors, ranges, ovens, and range vents are operated with normal controls only. Appliances are observed in normal use for conditions of deficiency and proper operation. Remaining life is undetermined. Future operation after the day and time of inspection is not warranted. Insurability for home warranty coverage is not determined or guaranteed.

**Sprinkler systems:**

Electronic controlled sprinkler systems are operated, when possible, in normal "test" or "manual" modes only. Condition of sub grade components remains undetermined. Sprinklers should be monitored for damaged heads, improper spray pattern, and clogged tips. The settings should be changed seasonally to aid in providing a consistent moisture level in the soil around the home. Excessive watering can be harmful to the foundation, may cause rot, moisture intrusion, or mortar erosion, and is conducive to insects including termites. Non-mechanical sprinklers (those that attach to exterior faucets) are not inspected. Coverage area or deficiency and quality / placement of installation is not inspected and undetermined.

**Swimming Pools:**

Pools can be unsafe. Select Inspect does not determine the safety of, quality of construction, life expectancy of any component, or condition of any inaccessible components. Drain and jet capacity is undetermined. Filters, heaters, electrical components, and valves are not disassembled. Computer controls and electronic valves are not inspected. Pool equipment is operated in normal service modes only. Safety of the pool and surrounding area is not inspected. Quality of the deck, shell or liner, and plaster / gunite is not inspected and is undetermined. Backwash provisions are inspected for presence where required, but are not tested. Condition and location of sub grade components including piping, electrical, and pool structure are not inspected and such is undetermined. Condition of decking is visually inspected only. The future performance or integrity of the decking system and any decking drains is undetermined. Fiberglass or vinyl liners are not inspected. Any comments regarding these pool types are limited and partial in context. Fiberglass and vinyl lined pools should be inspected by a pool specialist, familiar with that style of construction. Any pool related repairs should be made by a pool specialist, after full evaluation of the pool and equipment.

**Gas Lines & Gas Components:**

Carbon monoxide presence or potential is not inspected and is undetermined. If gas fueled appliances are present in the home, you are recommended to install carbon monoxide detectors per manufacturer and CPSC guidelines. Condition and type of inaccessible components including gas lines, connections, and inaccessible appliance components remains undetermined. Drafting and venting characteristics regarding gas appliances (natural or LP) are not inspected and remain undetermined.

**Environmental and Mold:**

The inspector is not asbestos certified, and will not positively identify asbestos materials. The inspector may denote materials that in his opinion are similar to or may possibly be asbestos-based or asbestos-inclusive. The inspector may comment on moisture intrusion and visible fungal growth found in the home, though we do not test for mold. Regarding visible fungus (mold, mildew, etc.): we do not determine mold type, determine if it is active or dormant, or quantity (PPM). Mold requires moisture to grow; areas that mold are commonly found include, but are not limited to: air ducts, air registers, and plenums; inner and outer air-conditioner components; below or behind sinks, flooring, and cabinets in bathrooms and kitchens; under flooring; wall voids; behind plumbing components; crawl spaces; poorly ventilated attics; synthetic stucco walls; "hard-board" type exterior walls, water heater areas, and fenestrations (windows & doors). Select Inspect did not take fungus or air samples from the home. If you are concerned about health related issues, we recommend that you consult an indoor air quality firm prior to purchasing the property for evaluation and options for cleaning. Please note that although there are many firms conducting this type of service, many are reputable and reasonably priced, while others may be found to be extremely high cost for similar work. Researching and evaluating various firms and their methods for remediation would be prudent, if you plan to pursue those measures. Select Inspect does not determine past flooding, moisture intrusion, or all leakage histories, and cannot determine if the home will flood or have moisture intrusion or leakage issues in the future. Refer to the seller's disclosure for possible information regarding moisture intrusion and leakage history of components and conditions at the property. Some insurance companies will not insure homes with prior flooding or water / mold damage claims or history. If the history of the home is suspect, you should contact your insurance provider to ensure the home and components will be insurable without exception, prior to closing.

If you have concerns about asbestos, radon, mold or other environmental issues at the property, you should contact a specialist. If possible, you should choose a contractor registered and certified by the Environmental Protection Agency (EPA). Websites related to these concerns are: <http://www.epa.gov/iaq/ia-intro.html>; and indoor air quality links from the Texas Department of Health (TDH) can be found at: <http://www.tdh.state.tx.us/beh/iaq/iaqlinks.htm>.

**Other**

Select Inspect aims to be the best in the industry. We perform our services with due diligence, commitment, and pride in our company. However, there are conditions that can prevent Select Inspect from being perfect and error free; such as, distractions from other persons or animals at the property, weather conditions, obstructions of stored items inside and out, inaccessible areas, including but not limited to wall voids, attic and crawl space areas, and underground or geological conditions. Therefore, we cannot and do not guarantee that every condition will be discovered. This is a general inspection, though in every attempt, a thorough inspection. If you have specific areas of concern, or desire to alleviate all questions of liability, there are specialized inspections from tradesmen in each specific field that may offer warranties and life expectancy quotes.

Select Inspect does not guarantee to discover or identify and report any recalled components that may be present at the property. If the inspector discovers a component that he suspects to be involved in a recall, he will attempt to include discovered information in a related section of your report. When possible, links to extended related information will be included in the report, and in all cases, it is recommended that you check the Consumer Product Safety Commission (CPSC) website at <http://www.cpsc.gov>, and consult a licensed specialist in the related field, when you have concerns about a component; even if it was not specifically mentioned in your report.

Many home warranty companies will deny claims based on preexisting conditions, excessive corrosion, systems and components that were / are "not to code", "not to manufacturer specifications", or near / at / past their expected lifespan. To reduce the risk of being turned down on a claim, it is recommended that you have a representative from your home warranty company examine the home and components to verify they will offer coverage without exclusion on all components you want covered in the policy. The Texas Real Estate Commission and your agent may have a list of recommended home warranty companies to choose from. Coverage is usually very limited, and you should read and understand their fine print, before choosing a provider. Reliance of information within this document by third parties is not permissible. **This report is non-transferable and is not to be used for insurance or warranty underwriting or reference by third parties without written consent from Select Inspect.** This report does not cover all information regarding issues and conditions that home warranty or insurance providers use to determine coverage.

**Definitions**, per the Texas Real Estate Commission 2008-2009 Standards of Practice (SOP)

- (1) Accessible--In the reasonable judgment of the inspector, capable of being approached, entered, or viewed without: (A) undue hazard to the inspector;
- (B) moving furnishings or large, heavy, or fragile objects; (C) using specialized tools or procedures; (D) disassembling items other than covers or panels intended to be removed for inspection; (E) damaging property; or (F) using a ladder for portions of the inspection other than the roof or attic space.
- (2) Chapter 1102--Texas Occupations Code, Chapter 1102.
- (3) Cosmetic--Related only to appearance or aesthetics, and not related to structural performance, operability, or water penetration.
- (4) Deficiency--A condition that, in the inspector's reasonable opinion, adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb, or property as specified by these standards of practice. General deficiencies include but are not limited to inoperability, material distress, water penetration, damage, deterioration, missing parts, and unsuitable installation.
- (5) Deficient--Reported as having one or more deficiencies.
- (6) Inspect--To look at and examine accessible items, parts, systems, or components and report observed deficiencies.
- (7) Performance--Achievement of an operation, function, or configuration consistent with accepted industry practice.
- (8) Report--To provide the inspector's opinions and findings on the standard inspection report form.
- (9) Specialized tools--Tools such as thermal imaging equipment, moisture meters, gas leak detection equipment, environmental testing equipment and devices, elevation determination devices, and ladders capable of reaching surfaces over one story above ground surfaces.
- (10) Specialized procedures--Procedures such as environmental testing, elevation measurement, and any method employing destructive testing that damages otherwise sound materials or finishes.

Photographs within this document are of limited components and or conditions that may have been noted as "deficient". These are included to be used as a partial visual aid in assistance for a better understanding regarding some of the components / conditions that were noted in the inspection report. All "deficient / correction recommended" comments in the main report are not pictured here; some of these images may include more than one condition. For information regarding details of the components or conditions in the following images, refer to the body of the main report, the Limitations pages of this report, and the "Guide to Your Home Inspection". This document is not to be used without the other pages and documentation related to the Property Inspection Report.

Thank you for your business. The greatest compliment I can receive is a referral from you to a family member or friend. When you meet someone buying a home, please remember to mention Select Inspect. Please call 214-770-6954 if we may be of further service.

If Thermal images are included; the following applies:

Thermal imaging is a technology that allows the INSPECTOR to show things about a building that cannot be seen with the naked eye. It is NOT x-ray vision, CANNOT see through walls, & is NOT 100% accurate. Thermal imaging offers an advantage to the educated inspector & client to ASSIST this inspector in discovering anomalies that can be used in further investigation to aid in the discovery of deficiencies. This is not a mold inspection; This service will NOT identify all deficiencies at the subject property. Thermal imaging produces images of invisible heat energy emitted from objects and systems in the building. Thermal imaging helps to diagnose the problem rather than merely identify symptoms and can sometimes, but not always, aid the inspector in locating & identifying deficiencies such as, but not limited to: Electrical faults, moisture intrusion, deficient building insulation or other components/materials, heat loss or other energy loss /efficiency conditions. The images can then be included in the inspection report providing supporting documentation to the report. Many images will be taken by the inspector; not all images will be included in the report, unless otherwise agreed to between the inspector & client prior to report preparation. Some interpretations are limited or inconclusive, because invasive measures were not performed to fully diagnose all conditions.

Refer to the temperature scale on the thermal image for variance within each image; please understand that even though there may be "many colors" within each image, such does not mean there is excess temperature variance, deficiency, or abnormal condition. There are multiple factors involved in evaluating each image. Some of these factors include, location in/on the building, structural modifications, ambient temperature, humidity, reflective component(s) in proximity to areas within the image, & other areas & or component(s) that may be more or less emissive within proximity to the areas that may or may not be pictured within the image(s).

Basically, when observing the Thermal images the following applies: brighter colors (red, orange, yellow, white, etc) have more heat & darker/blue-tone colors (blue, green, purple, etc) have less heat / cooler.

In summer/warmer months the bright colors generally imply heat infiltration at the interior; dark colors imply moisture intrusion or conditioned air loss at the exterior.

In winter/colder months the dark colors generally imply cold infiltration at the interior; bright colors imply moisture intrusion or heated air loss at the exterior.

Some electrical and mechanical components have a high heat or some energy loss signature simply due to the nature of their operation, & unless an unusual condition is discovered, would not necessarily be included in this report.

Refer to your "Contract & Service Agreement" for related information.

Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

**Report Identification 123 street; Allen, TX**

DIGITAL PHOTOGRAPHS; Supplementary to this Inspection Report



↑ master bathroom window has shifted outward & the bathtub(s) ledge has negative slope.



↑ moisture staining & worn mortar example at upstairs window



↑ worn mortar; openings



↑ example window separation



↑ veneer separation at the northwest



↑ close view of image at left



↑ example deficient guttering



↑ moisture intrusion; moisture damage



↑ moisture damage/rot in attic; adjacent the image above right



↑ close view of image at left- related images at top of page 38

Residential & Commercial  
Property Inspection

Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

Report Identification 123 street; Allen, TX



↑ low siding; deficient flashing; openings



↑ close view of image at left; moisture damage, inadequate converging valley slope



↑ unworkmanlike flashing; openings



↑ unworkmanlike shingles & flashing; openings



↑ moisture damage at roof deck; missing kick-out-flashing



↑ close view of image at left; rotting roof deck

Select Inspect™  
Residential & Commercial  
Property Inspection

Select Inspect © 2002  
This report is exclusive property of the client named on the cover page, and may not be used by others

Report Identification 123 street; Allen, TX



↑ uncaulked, exposed fasteners; example at water heater flue



↑ multiple deficiencies



↑ missing kick-out-flashing; rotting deck



↑ low siding; missing kick-out-flashing; rotting siding below eave



↑ inadequately secured flashing & nail



↑ inadequately secured flashing & nail

Select Inspect  
Residential & Commercial  
Property Inspection  
Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

Report Identification 123 street; Allen, TX



↑ impact damage at garage east



↑ tree damage, impact damage, & wear at master roof



↑ damaged roof ridge near chimney



↑ deficient flashing behind chimney



↑ missing kick-out-flashing; chimney north



↑ missing kick-out-flashing; chimney south

Residential & Commercial  
Property Inspection

Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

Report Identification 123 street; Allen, TX



↑ moisture damage; east eave



↑ uncaulked, exposed fasteners & unworkmanlike flashing; openings; & rodent gnawing evidence



↑ damaged shingles at valley over image pictured above



↑ soot at furnace flue & damaged shingles



↑ opening at shingle; example

Select Inspect™

Residential & Commercial  
Property Inspection

Residential & Commercial  
Property Inspection

Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

Report Identification 123 street; Allen, TX



↑ openings at shingles & uncaulked, exposed fasteners



↑ impact damage at shingles & flue cap & openings at shingles; example



↑ impact damage example



↑ unusual full shingle tab at ridge; upper southwest



↑ example deficient plumbing vent collar; moisture intrusion point



↑ close view of image at left; openings



Select Inspect © 2002  
This report is exclusive property of the client named on the cover page, and may not be used by others


Report Identification 123 street; Allen, TX



↑ deficient ridge shingles; northeast



↑ energy loss at attic accesses; example at ladder



↑ Thermal imaging from square at left




↑ missing access to this attic space; Conditions in not readily accessible/inaccessible locations remain undetermined; ie. Water heater flue, moisture stain source, electrical, framing, etc

Inspect™  
Residential & Commercial  
Property Inspection

Select Inspect © 2002  
This report is exclusive property of the client named on the cover page, and may not be used by others

Report Identification 123 street; Allen, TX




↑ there should be a minimum 24" pathway to the HVAC from the top of the access & 30" unobstructed service area, with no gaps or obstructions & this gas pipe section was inadequately secured



↑ unprotected gas components & HVAC drain piping & flue impeding attic access; unworkmanlike & unsafe




↑ Thermal imaging shows energy loss & or moisture evidence above the foyer



↑ Thermal imaging from square at left




↑ suspect inadequate seal at HVAC register/boot/duct- study



↑ Thermal imaging from square at left




↑ suspect inadequate seal at HVAC register/boot/duct-kitchen



↑ Thermal imaging from square at left



↑ Thermal imaging implies energy loss or moisture intrusion (staining & repair evidence discovered at this location) at master



↑ Thermal imaging from square at left

Residential & Commercial  
Property Inspection


Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

Report Identification 123 street; Allen, TX




↑ Thermal imaging implies energy loss at vaults; example at master



↑ Thermal imaging from square at left




↑ Thermal imaging implies energy loss & or moisture at master bathroom (staining present during the inspection); deficient plumbing vent discovered above at roof




↑ Thermal imaging from square at left



↑ Thermal imaging implies energy loss at master bathroom



↑ Thermal imaging from square at left



↑ Thermal imaging implies energy loss at northeast bedroom

↑ Thermal imaging from square at left



↑ caulking/sealant needed atop shower tile/panels; example

Select Inspect™  
Residential & Commercial  
Property Inspection

Select Inspect™  
Residential & Commercial  
Property Inspection



↑ Thermal imaging at front door


↑ Thermal imaging at patio door



↑ & window “tempered” etch not seen- may be labeled, though windows were unclean



↑ master patio door



↑ Thermal imaging at master patio door



↑ Alarm holes at the lower portion of the window may allow moisture intrusion; caulk and monitor



↑ window(s) lower than 24" interior & higher than 72" exterior; example

Select Inspect © 2002  
This report is exclusive property of the client named on the cover page, and may not be used by others

Report Identification 123 street; Allen, TX



↑ missing handrail at upper stair section



↑ grounding electrode protrudes grade; deficient

↑ close view of image at left




↑ incorrect location of air conditioning condenser(s) service disconnect; inadequate clearance of electrical panel for service personnel; old condenser is low & corroded; right condenser has hail/impact damage



↑ high water pressure at home & buried components at front garden



↑ close view of image above; Shut-off-valves require 3" clearance from soil



↑ unworkmanlike inoperable drain stop; upstairs bathroom



↑ deficient refrigerant insulation joint & leakage evidence above moisture staining at southwest bedroom



↑ corrosion at auxiliary pan & deficient refrigerant insulation; air conditioning primary condensate drain should be insulated; upstairs HVAC



↑ close view of image above right; moisture staining at attic insulation



↑ air conditioning primary condensate drain should be insulated; moisture staining at floor & attic insulation; corroded evaporator(s) & auxiliary pan; inadequately sealed joints- downstairs HVAC




↑ both flues did not meet clearance requirements to combustibles & moisture intrusion from roof




↑ moisture staining at insulation & framing; moisture staining at east bedroom ceiling below this location

Select Inspect © 2002  
This report is exclusive property of the client named on the cover page, and may not be used by others



Manufactured Duct Support

↑ inadequate support of air ducting; example



Stretch Manufactured Ducts

↑ crimped air ducting; example



↑ inadequate insulation & seal, & inadequately secured air duct to plenum; example at downstairs HVAC

↑ close view of image at left; energy loss

Residential & Commercial Property Inspection

Select Inspect © 2002


This report is exclusive property of the client named on the cover page, and may not be used by others

Report Identification 123 street; Allen, TX



Select Inspect Property Consultants, LLC

↑ flue too low/too close to wall; water heater





Gas Appliance Vent Terminations



Select Inspect Property Consultants, LLC

↑ temperature/pressure relief drain improperly routed uphill; unworkmanlike installation



Select Inspect Property Consultants, LLC

↑ drain for the dishwasher was improperly routed uphill; this should gravity drain from the backflow device;




disposal was corroded at the interior & had some visible corrosion at the exterior canister & electrical clamp was inadequately secured


exhaust fan(s) improperly terminate in the attic, rather than exterior

Select Inspect © 2002

This report is exclusive property of the client named on the cover page, and may not be used by others

Report Identification 123 street; Allen, TX





- G= WOOD-on-GROUND      I= FORM Board / Stake      J= MOISTURE      K= WOOD Debris      L= HIGH SOIL      M= WOOD DECAY
- N= DENSE FOLIAGE      O= SOIL Filled Planter      Q= WOOD PILE      R= FENCE Touching Bldg      T= INADEQUATE VENTILATION
- A= ACTIVE      P= PRIOR (EVIDENCE)      S= TERMITES      H= CARPENTER ANTS      B= OTHER WOOD-BORING INSECT
- ⊗ = treatment evidence; bait, drill, trap, etc      □ = 2 - 3 FEET      ~ = Visual slab/concrete crack

↑ diagram of exterior structure